4L60-E

PMW UNITS

Part No. SC-4L60E





onnax Sure Cure® Kits combine "the best" Sonnax products into one box, offering rebuilders a convenient and costeffective way to address common transmission problems. These kits simplify ordering, stocking and estimating job costs,

Da

d e

Rebu

77917-TL

and include easy-to-read, step-by-step instructions that cover the inspection and repair of the most critical areas of the unit, and even a reference list of rebuilding specifications.

This 4L60-E transmission reconditioning kit includes the following Sonnax parts and addresses these problems:

Sonnax Part:	The SureCure® for:
 TCC regulator valve assembly (77754-04K) 	Code 1870 & harsh 1-2 shift
 Actuator feed limit valve assembly (77754-09K) U.S. Pat. No. 6,634,377 	Wrong gear starts, solenoid codes & no 4th gear
 Accumulator pistons (1-2, 4th) (77998-03K) 	Poor shift feel, band failure
Boost valve assembly (77898E-7K)	Poor line rise & 3-4 clutch failure
• TCC apply valve kit (77805E-K)	Falling out of lockup
 Oversized pressure regulator valve (77917-07) 	Low line pressure & 3-4 clutch failure
• Servo check valve (77701-076)	3-4 clutch failure & poor 2-3 shift feel
• Pump slide pivot pin (65797)	High line pressure at idle
 Teflon[®] coated pump bushing (77005T) 	Front seal leakage, converter hub wear
Accumulator spring (74926)	Replacement for broken OEM spring
• Imidized checkballs (10000-08)	Ball seat leakage & premature ball seat wear
D-ring servo seals	2-4 band failure
• Endplay shims (77406-10 & 77409-15)	Excessive unit endplay
Valve body retainer clip (77754-08)	Replacement for broken OEM clip
• Forward or reverse abuse valve bore plugs (77754-21)	3-2 tie up or delayed reverse
• 3-4 relay valve end plug (77764-07)	Common end plug leakage
Required Tools:	
77754-R2	Reamer for TCC regulator valve
77754-TL	Tool kit for AFL valve

©2003 Sonnax® SC-4L60E (rb) 01-16-08

Tool kit for pressure regulator valve