180C (3L30)

PART NUMBER 54251-02

OEM steel governor sealing rings wear the aluminum bore.

This governor bore sleeve restores hydraulic integrity to the case.

Governor **Bore Sleeve**


54251-02 1 Governor Bore Sleeve



Note: Requires advanced machining.

Wrong gear starts

• Case wear at the governor hub seal area



Sonnax Part Summary

Vehicles with GM 180 (3L30) transmissions frequently have excessive wear at the governor hub seal area. These units use steel seal rings against an aluminum bore. Because these components are often found in high-mileage vehicles, excessive wear in the sealing ring area leads to fluid leakage and can destroy the case. Sonnax now offers this wear-resistant governor bore sleeve 54251-02.

Features & Benefits

- Sleeve is made from hardened and ground steel and prevents excessive wear.
- Sleeve salvages worn cases and restores hydraulic integrity.

