4T40-E, 4T45-E

PART NUMBER 33886-03K

Boost Valve and Sleeve

33886-03K

1 Boost Valve

1 Sleeve

Associated Parts


33000-02

TCC Regulator Apply Sleeve



33000-TL

- 1 Core Drill
- 1 Drill Guide
- 1 Reamer
- 1 Reamer Guide



Wet Air Test:

To Wet Air Test the boost valve assembly, place a small amount of oil into the torque signal port. Follow with low air pressure. There should be little or no leakage past the boost spool and out the reverse port. Place a small amount of oil into the reverse boost port. Follow with low air pressure. There should be little or no leakage past the boost spool and out the torque signal port.

Installation Instructions:

- 1. Discard both the OEM boost sleeve and valve.
- 2. Replace with Sonnax boost valve assembly.

