

Converter Code Calamities

o you have that 4L60-E back again for harsh 1-2 or Code 1870 complaints? Or maybe it is a Chrysler mini-van back with repeat planetary failure. Whatever the converter related failure, Sonnax will most likely have a solution. Rather than spend hours rummaging through your core pile or spending hundreds on a new valve body we have the cost effective solution that will fix the problem the first time. Reference this list to find a quality engineered TCC solution for your application and to get your customer happily back on the road.

App./Part # Description

Helps Cure

Codes 1870, 740, 039, 68,

Falling out of lock up hot

Blued or burnt converters

Codes 62, 628, 1741, 1744,

converter shudder and over-

Converter lining failure, con-

verter shudder, unit overheat,

high line pressure, Poor lube

Engine stall during stop or on N

to D engagement

pressure

control

heat, Improved converter apply

Harsh 1-2, Converter shutter,

4T40-E 33000-02* 4T60 & E 84754-16K* 84754-22K 84754-01K 84754-08K* 84754-97K* 84754-98K	TCC Regulator Apply Valve Kit TCC Apply Valve, Oversized with Teflon® Seal ('91-'96) TCC Apply Valve, Standard with Teflon® Seal ('93-'96) TCC Regulator & Isolator Valve Kit ('93 & Up) TCC Regulator & Isolator Valve ('91 & '92) TCC Apply Valve Kit, Aluminum, Oversized ('97 & Up) TCC Apply Valve Kit OEM Aluminum, Standard ('97 & Up)	Codes 1870, 740, 039 Converter shudder Blued or burnt converters Falling out of lock up "hot"
4T65-E 84754-34K* 84754-43K	TCC Regulated Apply Valve Kit TCC Control Valve Kit	TCC Slip, Code 1870
4L60 & E	(PWM and NON-PWM)	

7 7 000 IX	100 Apply valve, oteel with fellon ocal	
77805E-K	TCC Apply Valve, Aluminum with Teflon® Seal	
77754-03K*	TCC Regulator Valve Kit '92-'97 Units (Includes Non-PWM)	
77754-04K*	TCC Regulator Valve Kit '97 and Up EC ³ Units	

77754-ISO* Isolator Valve Sleeve Repair Actuator Feed Limit Valve Kit 77754-09K*

4L80-E 34994-01K TCC Regulator Valve Kit 34200-16K* Actuator Feed Limit Valve Kit

E40D

36424-04K Line-to-Lube Pressure Regulator Valve

4R100

36424-08K TCC Control Sleeve Assembly

AXOD

Bypass Clutch Control Sleeve & Plunger Valve 96201-06K

AXODE, AX48

Bypass TCC Control Valve & Sleeve Kit 96206-01K

AX4N 96206-03K

AODE, 4R70W

76948-04K Bypass Clutch Control Sleeve & Plunger Valve

CD4E

73840-BK* Bypass Kit, Bypass Valve and Bypass Sleeve and Plunger

Bypass Clutch Control Sleeve & Plunger Kit

41TE, 42LE

Converter Regulator Valve Kit 92835-03K 92836-01K Bypass Plug

92835-07 Pressure Regulator Sleeve

42/46/47RH/RE

4 Spool Switch Valve 22771A-01

VW 01M, 01N, 01P, 099

119940-01K TCC Boost Valve Kit

* These parts require reamers.

