

Condition: Weak pump or clogged filter.

Correction: New pump with Sonnax Boost Valve Kit **34910-01K**, Sonnax Pressure Regulator Valve **34910-03K** and a new filter.

Notes: Flow drops off dramatically with lower engine rpm.