



## **TORQUE CONVERTER PARTS**

## **MACH-FRC**

## FRICTION RING CUTTING MACHINE

#### **Details:**

 This friction ring cutting machine can be used to produce custom sized friction rings from Sonnax/Raybestos master rings.

#### **Associated Parts:**

- 10000-84 replacement cutting wheel
- Master Rings:

Part Number	Dimensions	I hickness/Material
RMR1245	12" X 6"	.045" Tan
RMR1275	12" X 6"	.075" Tan
RMR1344HC	13" X 6.125"	.040" High Carbon
RMR1374HC	13" X 6.125"	.070" High Carbon
RMR1345	13" X 7"	.045" Kevlar
RMR1375	13" X 7"	.075" Kevlar
RMR1366	13" X 7"	.066" PowerTorque



#### Part No.

## **MACH-FRC**

Friction Ring Cutting Machine

### Sold in prepackaged quantities of 1 unit

Please refer to our

# TORQUE CONVERTER PARTS CATALOG VOLUME 6 & ONLINE CATALOG AT WWW.SONNAX.COM MACH FRC:

Should be used to replace and update Page 394.



Sonnax again offers this Friction Ring Cutting Machine for producing custom sized friction rings from Sonnax/Raybestos Master Rings. Instructions for making holding fixtures are included and can also be downloaded at www.sonnax.com.

©2008 Sonnax Industries, Inc. MACH-FRC 12-06-08



# **TORQUE CONVERTER PARTS**

## **MACH-FRC**

## FRICTION RING CUTTING MACHINE INSTRUCTIONS


The friction ring cutting machine MACH-FRC does not directly accommodate the Sonnax/Raybestos Master Rings which have large inside diameters. Centering disks will be needed to support and hold them on center when cutting. Below is a sketch of the three stepped centering disks needed for cutting master rings. The ¾" hole must be on center to the stepped diameter. These can be made out of aluminum, steel, Plexiglas, or fiberboard. A ¾" diameter by ¾" long shoulder screw will be needed to hold the disk on the cutter and the screw threads will have to be cut to length shown.

A quick alternative is to use a cardboard disk with a %" hole in the center. The cardboard disk should be about ½" larger than the inside diameter of the master ring. The Raybestos Master Rings should be taped on center to the %" hole so it runs true. The tape should be applied close to the inside diameter so as not to damaged the friction material surface used. A weight, such as a turbine hub, can be placed on the center of the cardboard disk to prevent the disk from lifting when cutting.

#### **Master Rings**

Part Number	Dimensions	Thickness/Material
RMR1245	12" X 6"	.045" Tan
RMR1275	12" X 6"	.075" Tan
RMR1344HC	13" X 6.125"	.040" High Carbon
RMR1374HC	13" X 6.125"	.070" High Carbon
RMR1345	13" X 7"	.045" Kevlar
RMR1375	13" X 7"	.075" Kevlar
RMR1366	13" X 7"	.066" PowerTorque

#### **Friction Ring Cutter Centering Disks for Master Rings**



©2008 Sonnax Industries, Inc. MACH-FRC 12-06-08