JATCO/NISSAN

PART NUMBERS 113741-09K, F-113741-TL9

Chatter on acceleration, High or low line pressure

SECONDARY COMPLAINTS

Wear of the primary pressure regulator bore minimizes line pressure control. Depending on the severity and location of bore wear, main line prssure may be too high or low, resulting in problems such as pullley breakage or chatter on acceleration.

Refurbish the valve bore and install the Sonnax valve, spring and end plug to restore accure pressure control.

Oversized Primary Pressure Regulator **Valve Kit**

113741-09K



- 1 Oversized Pressure Regulator Valve
- 1 Spring
- 1 End Plug


NOTE: Fits JF010E & JF011E

F-113741-TL9

- 1 Reamer
- 1 Reamer Jig
- 1 Guide Pin



• Slip forward or reverse • Pulley breakage • Loss of valve body core





Features & Benefits

- Sonnax pressure regulator valve is hard-coat anodized aluminum to increase wear resistance.
- Sonnax replacement spring maintains OEM calibration.

You need this if...

Either a vacuum or wet air test in the location shown results in leakage. Vacuum test must hold a minimum of 18".







©2010 Sonnax Industries, Inc.

113741-09K Rev:-, F-113741-TL9 Rev:-, 113741-09K