PART NUMBERS 22754N-01K, 22754N-02K

# **Upgraded Piston Retainer**

## 22754N-01K

Standard Diameter 46-47RH/RE 6-Bolt Piston Retainer

## 22754N-02K


Oversized Diameter 46-47RH/RE



6-Bolt Piston Retainer

**Note:** Oversized diameter allows damaged reverse drum to be salvaged.

Note: U.S. Patent No. 6,810,771





### PART NUMBERS 22754N-01K, 22754N-02K

### **Installation Instructions**

- 1. If the oversized support (larger diameter where drum rides) is being used, turn the reverse drum I.D. to 2.1885"/2.1875". It is important to achieve a surface finish of 16 Ra (comparable to a ground finish) or smoother to increase the life of the unit.
- 2. It is recommended that you drill a small .040"-.045" hole in the case to help lubricate the low roller clutch. See Figure 1 for the exact location of the hole. This process is not a requirement to use the Sonnax retainer.
- 3. Install the o-ring into the o-ring groove and lubricate with TransJel®.
- 4. If the retainer is being installed on a RE unit, press the two aluminum plugs into the governor tube holes (see Figure 2).
- 5. Assemble the transmission following normal procedures.
- 6. The SonnaFlow® should be used to verify cooler flow after the rebuild (see Figure 3).





Figure 2



Installing the two plugs included with the retainer allows for use on an RE (computer-controlled units).

Figure 3
Problems Diagnosed by SonnaFlow™



47RE Poor ••••
Restricted Radiator
OEM Valving

47RE Good New Radiator
Updated Valves



Some cases vary in the size of their bore where the area below the o-ring rides. You should not try to drive or press the support into the case. If the support will not fit by hand (you may need a little pressure), you will have to hone about .005" off the I.D. of the case bore.

Do not to stake the plugs: staking the plugs can cause leaks between the support and case.

