PART NUMBERS 36008A & C, T36605-03 & -04, T36008A

# Spun-out bushings and case damage



Lack of lubrication, excessive journal clearance, or too much load for the bearing area.

This one-piece, oversized rear case bushing installation system can replace a spun-out bushing and save expensive cases once the bushing bore is accurately machined.

# **Oversized Rear Case Bushing** Installation **System**

Early Design Style: 3 Grooves to Front 36008A C6 & E4OD ('89-'94)

4 Oversized Bushings



Late Model Design: 3 Grooves to Front, 1 to Back

36008C

4 Oversized Bushings



## T36008A


1 Bushing Installation Tool

### T36605-03

1 Reamer

# T36605-04

1 Reamer Fixture



## Sonnax Part Summary

The OEM rear case bushings in the Ford C6/E4OD/4R100 transmissions tend to spin out, causing damage to the case. After the case is damaged, it is impractical to reinstall a standard bushing. Bushing spin-out may be due to lack of lubrication or too much load for a given bearing area. Sonnax has developed an oversized bushing installation system specifically designed for these applications.

### **Features & Benefits**

- Bushings available for both 3-groove early design style and 4-groove late model designs.
- Both one-piece replacement bushings are an improvement over the OEM two-bushing design because of their increased bearing surface area and superior lubrication characteristics.
- System includes a custom-designed 1%" reamer, reamer fixture and installation tool.



\$400 in case replacement costs

