PART NUMBER 77731-09

COMPLAINT

Thrust bearing in rear planetary fails



Thrust loads from gear train and output shaft and poor quality replacement



Install this new OEM quality replacement bearing.

Rear Planetary Thrust Bearing

77731-09

Thrust Bearing

Note: Planetary pinions must be removed for installation


Also available

77731-RK

Rear Planetary Rebuild Kit

77731-02K

Pinion Pin Kit



Sonnax Part Summary

Part 77731-09 is direct OEM replacment for the rear planetary captive thrust bearing.

Features and Benefits:

- Bearing not available from OEM.
- Allows salvage of old planets with worn bearings.

\$80 in planet replacement costs

