GM '69-UP THM180, ALL 3L30 AND 4L30-E

MANUAL VALVE LINK

Features & Benefits:

- Design reduces susceptibility to cracking
- Eliminates inspection of used links
- Direct replacement in OEM application

Part No. 54250-01

1 Manual Valve Link



PART SUMMARY

Sonnax part **54250-01** is a direct OEM replacement for cracked, broken and missing manual valve links. Used OEM parts can fail shortly after being put back into service. By installing new manual valve links, these failures can be eliminated.

92004 Sonnax° 54250-01 06-16-04