




FD-DA-13

Ford 4R100 Multi-Plate Clutch Assembly



- OEM replacement
- Multi-plate design
- Balanced assembly
- O.D. 12.156"

Associated item: **FD-CC-16** OEM grob front cover

Please Refer To Our

Torque Converter Parts Catalog 2000

FD-DA-13 is:

• Item Numbers 20, 21 and 22 of Reference Figure 2.17 on page 74.



Sonnax now offers **FD-DA-13**, an OEM replacement for the multiplate clutch/damper assembly used in the Ford 4R100 torque converter. This assembly mates with Sonnax **FD-CC-16** grob OEM front cover.

Note: This component works in applications with PTO units, which have non-seal ring style turbine hubs, and should not be used with seal ring style applications.

© 2002 SonnaxTM Mar '02