**PART NUMBER 96201-15K** 

# Valve Saver Cap

### 96201-15K

5 Valve Saver Caps

5 Retainer Clips


US Patent No. 6,722,385

Also Available

### 96201-10

Retainer Clip

Note: These retainers are applicable to numerous Ford valve body locations.



#### **Installation Instructions**

- 1. Remove the pull-in assembly and clip to get to the 3-2 control valve.
- 2. Remove the 3-2 timing valve to verify it is not bent and ensure stroke action is complete.
- 3. Verify that the Sonnax valve saver cap 96201-15K will be able to move freely over the end of the valve.

**Note:** Assemble with Trans-Gel<sup>™</sup> to keep the cap from coming off the valve during installation.

## **Reassembly Overview**

- 1. OEM 3-2 shift valve, Sonnax Valve Saver Cap
- 2. OEM Spring, Sonnax Retainer Clip
- 3. OEM Spring
- 4. OEM Pull-in Valve
- 5. OEM End Plug
- 6. Sonnax Retainer Clip

