PART NUMBER 84450

COMPLAINT

Worn-out bearing



Normal wear causes bearing to fail.



Replace the worn out bearing with this new 4th clutch hub bearing.

4th Clutch Hub Bearing

84450

1 Bearing



Sonnax Part Summary

In 4T60 & E transmissions, the bearing in the 4th clutch hub shaft ("cookie cutter") often fails, making it necessary to purchase a new and expensive clutch hub. Sonnax now offers an OEM replacement clutch hub bearing **84450** that allows you to salvage the original clutch hub.

Features & Benefits

- Easy to install.
- Salvages expensive clutch hubs.

Note: Although the OEM applications are for '94 & '95, the shaft with this bearing and the external sleeve on the opposite end can be used back to '83.

