PART NUMBERS F-77754-TL4, F-77754-SERV

# Inconsistent reaming results, difficulty reaming valve body

# LAUSE

Variables such as casting circuit length, reaming speed and process control contribute to inconsistencies in reaming this bore.

Used in conjunction with the Sonnax valve body reaming fixture VB-FIX, these tool kits allow for consistent reaming and ease of use.

# **TCC Regulator** Valve Tool Kit

### **NEW PRODUCT!**

### F-77754-TL4

- 1 Roughing Reamer
- 1 Finishing Reamer
- 2 Reamer Jigs
- 1 Guide Pin
- 1 Stop Pin



## **SERV Tool Kit**

F-77754-SERV

1 Roughing Reamer 1 Guide Pin





Note: Use F-77754-SERV with F-77754-TL4 on previously remanufactured valve bodies.

New products above used for installation of the following kits:

77754-03K Elevated apply/firmer TCC

77754-04K

OEM apply for EC3

Each kit includes th e following

- 1 Isolator Valve
- 1 Sleeve
- 1 Regulator Valve
- 1 Spring

### 77754-ISO

- 1 Isolator Valve Sleeve
- 1 Retaining Clip





#### Sonnax Part Summary

These new tool kits, F-77754-TL4 & F-77754-SERV, are designed specifically for reaming the TCC regulator and isolator bores in conjunction with the valve body reaming fixture, VB-FIX. F-77754-TL4 & F-77754-SERV do not replace or supercede the existing tooling 77754-R2, 77754-RM5 or 77754-SERV, but are upgraded systems that make use of the Sonnax valve body reaming fixture to ensure that the reamer is being piloted concentric with the bores. The TCC regulator valve tool kit F-77754-TL4 makes it possible to prepare the bore to accept the 77754-03K, -04K and -ISO regulator and isolator kits in valve bodies that have not been remanufactured by GM. The tool kit F-77754-SERV, used in conjunction with the **F-77754-TL4** tool kit, services bores in valve bodies previously remanufactured by GM.

#### **Features & Benefits**

- Tool kits consistently align reamer with TCC regulator and isolator bores for complete wear clean-up.
- Tool kits size bores for Sonnax valve kits 77754-03K, -04K and -ISO.
- Used together, these kits allow GM-remanufactured units to be serviced.