
SC-4L60-E Verification Procedures


Exhaust 4th 3rd 2nd


With servo bore resurfaced and Viton® seals on piston, install and air test. There should be no cross leakage from opposing circuits (when testing 4th there should be no leakage from 3rd, etc.).

Doing this WAT test before unitre-assembly will identify leakage of 3rd accumulator capsule, servo pin or bore. Locating a problem now could save an additional tear-down. With fluid in servo, WAT. No leakage from 3rd capsule and/ or servo pin bore.



Orificed vent; slight bleed with fluid and air psi of 30-60 is normal.





©2006 Sonnax Industries, Inc. SC-4L60-E 12-05-06