
4L80-E ('99)



Event: Drive idle, hot (minimum)

Condition: After converter crowding repaired.