



## TORQUE CONVERTER TECH ADVISORY



January 2010

## Visual Variations on the Ford Clutch Plates for 5R55N/S/W, AX4N (4F50N) Converters: Sonnax Part Numbers **FD-CP-1** and **FD-CP-2**

The OE specification for **FD-CP-1** and **FD-CP-2** requires a carbonized surface treatment to enhance engagement performance and prevent break-in shudder. Following this surface treatment, the parts are coated with a rust inhibiting solution. As a result, it is typical for the parts to appear dark or "burnt".

Due to the process, you can expect to see varying surface colors; light, medium or dark appearance is normal and acceptable.

Raybestos continues to manufacture and supply these products for OE according to the written OE specifications. Ford continues to accept them with no performance or visual concerns.

