
## **E40D ('90 1-TON DUMP)**



**Condition:** Normal for early pump.

Notes: Drilling line to lube across pump will increase flow. A stock worn, weak pump may flow down to .4 in reverse at idle.