
5R55W 2003 LINCOLN LS 3.9L



Condition: Normal operation.

Notes: Internal thermal bypass will not open until approximately 125 degrees F. Once open, flow to cooler results. 5R55N units have 1/2" O.D. cooler lines. Transmission lower cooler line is the return line and most accessible at the radiator.