
AXODE



Condition: Incorrectly wired EPC and shift solenoids.

Notes: Notable "click-click" from side cover and 2nd gear shuttle.