TECHNICALLY Speaking

Article No.: TASC-TIP-02-2009

Author: Bob Warnke

Total Pages: 3

5L40/5L50E – Isolating the loss of Reverse or TCC concerns

The photo in Figure 1 shows a 5L40E valve body being tested on a valve body machine. The pressure used here is lower than normal operating pressures, but that made it possible to capture the many spurts and geysers erupting from the valve body. In reality, under normal operation, these spurts would be a pressurized spray. There are many exhaust points in

modern valve bodies and even, under the best of circumstances, this flying fluid traps and carries a fair amount of air with it on its way to the sump. This is expected and sumps and pickups are designed to deal with a certain amount of aeration.

As valves and bores begin to wear and allow leakage, the easiest path for the leak is to exhaust. Two things happen as a result of this wear induced exhaust

leak. First, the leak allows a pressure drop which is loss of control pressure. Valves or components no longer move, apply respond as intended. Second, the amount of exhausted fluid and therefore the amount of air entering the sump is increased. The amount of aeration can easily surpass the sump's ability to dissipate the air before the



Figure 1: 5L40E Operating Loss

pump picks it up. The minimal sump capacity of the 5L40E makes it especially vulnerable to this problem.

The chart below identifies Reverse or TCC complaints associated with the two pronged ailment created by wear and leakage. The illustrations and notes are in the order of service, beginning with in-vehicle, on to disassembly, bench inspection and ending with the preparation for Dynamometer or vehicle testing.

COMPLAINT	CAUSE	ISOLATION
TCC Slip Code Converter lining & fluid overheat TCC piston deflection	TCC regulator bore AFL bore Main regulator bore TCC solenoid quality Pump cross leaks	W.A.T. Vacuum testing Pressure gauges on TCC signal
Loss of reverse at high pressure	Reverse lock-out bore Wear valve body cross leaks	W.A.T. Vacuum testing Pressure gauge on TCC signal
Loss of reverse at low pressure	Defective TCC solenoid Reverse lock-out valve stuck outward	Isolation solenoid
Loss of 4-5 Wrong gear start TCC slip High pressure in reverse Clutch distress	AFL bore wear Main regulator bore	W.A.T. Pressure gauge on line tap. Check maximum reverse pressure Vacuum testing

sonnax

Automatic Drive P.O. Box 440
Bellows Falls, VT 05101-0440 USA
800-843-2600 • fax: 802-463-4059
email: info@sonnax.com •
www.sonnax.com

©2009 Sonnax Industries, Inc.

TECHNICALLY Speaking





Figure 2: Circuit Air Testing






Figure 4: Case Circuit Tests

With the oil pan removed and the Manual Valve in the Reverse position, apply 30 to 40 psi of regulated air into the main line pressure tap. This is referred to as a captive wet air test or W.A.T. The tap is located between the pan rail and the cooler lines. A good valvebody will have minimal fluid loss at the three locations indicated (see Figure 2).

Loss of Reverse at low pressure

It is common for the filter to eventually break as a result of contact with the valve. Filter fragments migrate to the Reverse Lockout bore and cause the valve to stick towards the retainer (Figure 3).

Loss of Reverse at high pressure

Cross leakage into the TCC signal circuit can partially stroke of the Reverse Lockout and TCC enable valves. Cross leaks may occur at the pump surface, TCC solenoid, TCC regulator bore, a warped valve body surface or the Reverse Lockout valve. When TCC signal circuit pressure reaches 5-7 psi, the Reverse Lockout valve will have moved enough to restrict reverse. At 10-12 psi the TCC control and enable valves are positioned to restrict converter release oil flow.

A used TCC solenoid can be modified for a test tool, or a fixture can be made to duplicate the OE manifold. To use a solenoid, remove the coil and both screens, and then plug the port that had the wrapped screen. If you can make your own test manifold, make a through-hole that exits at the TCC valve and tap the outer end for a removable plug. This tool can be used in a functioning unit, so a removable end plug allows you to verify pressure buildup.

Using the test tool on a bench unit, apply low air pressure to the outer end. Air flow should only exit at the TCC regulator valve and into the TCC signal circuit.

During the air test, the TCC enable valves (located in the pump) and Reverse Lockout should stroke and no leakage should be seen at the TCC regulator bore. If the Reverse Lockout valve does not stroke, filter particles may be causing it to stick.

If you use the tool during a vehicle reverse pressure test, it can isolate valve body vs. pump issues. Install your test manifold, with the removable plug in through hole. If Reverse remains engaged at high pressure, the original TCC solenoid had a cross leak. If Reverse is still lost, the unit has a cross leak and circuits can be air tested through it the tool, to identify the source.

Case circuit testing

The case circuits shown (see Figure 4) can be air tested to identify pump cross leakage. Both circuits are dead-ended at the valves. When they are pressurized at 50-70 psi the valves should stroke, but no leakage should be seen from any other area. If it does leak, there is bore wear or pump warpage, which lead to TCC and clutch pressure problems.




Figure 5: Bore Inspection

Vacuum test possible, inspect for bore wear where indicated.




Figure 6: Pump Inspection




Figure 7: *Bell housing pressure taps*

These circuits can be drilled and accessed with pump/bell removed. Accurate gauge or Transducer should be installed.

Valve Body Bore Inspection

Figure 5 identifies valves of concern that have been isolated in previous tests. Once the casting is cleaned, these areas can be vacuum tested or the bore can be inspected for wear. The valves themselves rarely have any witness marks. Bore wear can be detected but it does require careful inspection. With a calibrated vacuum test station and proper valve to bore clearance, these circuits should retain at least 18" of vacuum.

Pump Inspection

Once the unit has been disassembled, inspect the TCC enable bore and main pressure regulator bore (see Figure 6). Main regulator bore wear causes slide instability, pump/rotor damage, high pressure and TCC issues. Bore wear at the TCC enable valves' inner spool, causes overheated converters and high slip rates.

Bell housing pressure taps

If you have repetitive problems, or wish to verify TCC solenoid quality and control, tapping into the TCC circuit at the case bell (see Figure 7) will be a productive test. Tapping into these circuits identifies the amount of pressure within the TCC apply and signal oil.

If you perform this, use the precautions of the construction trade, "measure twice and drill once". The casting material is minimal but sufficient to access the ports with a Parker# 169PL-4-10X32 fitting. If you have not utilized this nylon tubing test before, also purchase a 169PL-4-2 and sufficient nylon tubing.

Bob Warnke is Sonnax Vice President of Technical Development and a member of the Sonnax TASC Force (Technical Automotive Specialties Committee), a group of recognized industry technical specialists, transmission rebuilders and Sonnax Industries Inc. technicians.

Article No.: TASC-TIP-02-09 Author: Bob Warnke Page 3