
BW-T65/66, BW-T35

PART NUMBER 29133-01K

O-Ringed Modulator Valve End Plug

29133-01K

1 End Plug 1 O-Ring



Wet Air Test

With the valve body still in the transmission (T-65/66 only), remove the governor and apply low air pressure to the governor oil circuit. Both shift valves will stroke. There should be no air/oil leakage past the modulator valve end plug.

If the valve body has been removed from the transmission (T-35/65/66), apply low air pressure to the governor port. There should be no air/oil leakage past the modulator valve end plug.

