
4L60-E ('94 NON-PWM)



Condition: Good flow and TCC valve action, flow increases by .2 gpm when hot.