REPLACEMENT PARTS **4L60 & E 1982-2002**

REACTION SUNSHELL

Features & Benefits:

• Direct replacement

Part No.

77749-01

1 Reaction Sunshell Unit Price: \$16.10

Also Available: Part No.

77010-01

1 Wide Reaction Sun Gear Bushing



PART SUMMARY

Sonnax 77749-01 is now available as a direct replacement for damaged OEM reaction sunshells.

INSTRUCTIONS:

- 1. Remove the damaged OEM reaction sunshell.
- 2. Inspect sun gear, input clutch housing and surrounding components for damage and replace as needed.
- 3. Install Sonnax 77749-01, using standard build procedures.