
41TE (A604)



Condition: Repeat switch codes, weak pump.

Correction: New pump, Sonnax TCC Regulator Valve 92835-03K, good valve body and bypass valve in case plugged.