Supplier Process Audit Report - Kessler Gusstechnik (Housing Castings)

Document no.	QR-AUD-2026-03	**Revision**	A
Document type	Audit Report	**Status**	Final
Effective date	2026-05-19	**Owner**	Supplier Quality
Classification	Confidential		

1 Audit data

Supplier: Kessler Gusstechnik, plant 2. Product: gearbox housing castings GH-210 (aluminium high pressure die casting). Audit type: process audit according to VDA 6.3. Audit date: 2026-05-12 and 2026-05-13.

2 Result

Overall degree of fulfilment: 78 %. Classification: B (conditionally approved). Two process elements were rated below 80 %:

Process element	Result
P5 Supplier management	82 %
P6.2 Process control during series production	71 %
P6.4 Measurement and test equipment	74 %
P7 Customer care	88 %

3 Main findings

1 Porosity check by X-ray is done on 1 part per shift only, while the control plan requires 1 part every 2 hours.

2 Two gauges used for the sealing face flatness were overdue for calibration by 3 months.

3 Reaction plan for vacuum system failure at die casting cell 4 is missing.

4 Required actions

The supplier must send an action plan within 10 working days. A follow-up audit is scheduled for November 2026. Until then, incoming inspection of GH-210 castings is increased to 5 parts per batch with X-ray. If the follow-up audit result is below 80 %, the supplier is put on new business hold.

CONFIDENTIAL