

P-101 Condition Inspection

Inspection reference IR-2026-0912 | 12 September 2026

Equipment and operating observation

Equipment: P-101 centrifugal process pump. Service: cooling-water circulation. Inspection performed at 10:30 IST by Maya Rao, Maintenance Inspector. Pump remained in controlled operation during non-contact observation.

Measured condition

Overall vibration at the drive-end bearing was 8.2 mm/s RMS. Discharge pressure was stable at 5.8 bar. A recurring liquid drip and wet patch were observed around the mechanical-seal area. No visible damage was observed on the coupling safety guard.

Immediate action

The operator placed P-101 under enhanced observation and notified the maintenance manager. No casing, flange, seal, or guard was opened during this inspection.

P-101 Condition Inspection

Inspection reference IR-2026-0912 | 12 September 2026

Requested decision

Review the inspection evidence against the approved maintenance SOP. Decide whether maintenance work may proceed and identify all isolation, pressure-verification, authorization, and escalation controls.

Inspection limitation

This is a visual and instrument-reading record, not proof of internal pump condition. Root cause, seal integrity, alignment, and bearing condition require responsible maintenance review after safe isolation.

Approval boundary

Any generated recommendation is a draft. The maintenance manager remains accountable for work authorization, personnel safety, and verification of the physical plant state.