

Safe Work Method Statement (SWMS) – Glass Wool Installation

Project Information

This SWMS applies to installation of Consolidated Energy Glasswool insulation in residential and commercial buildings.

High-Risk Activities

Working in roof spaces, working at heights, handling fibrous materials, working near electrical services.

Hazards Identification

Products are classified as Carcinogen Category 1B (H350 May cause cancer). Risk arises primarily from inhalation of respirable airborne fibres during handling and installation. Skin and eye irritation, electrical shock, falls, heat stress, manual handling injuries. SDS and Technical information available by scanning the QR bar code on the product label.

Control Measures

Use PPE, isolate electrical hazards, maintain clearances, provide ventilation, use safe access equipment, and follow manual handling procedures.

Personal Protective Equipment

Gloves, long-sleeved clothing, safety glasses, P2 respirator when dusty, safety footwear and hard hat where required.

Emergency Procedures

Stop work in case of incident. Provide first aid. Contact site supervisor. Seek medical attention if exposure occurs.

Training and Supervision

All workers must hold White Card, receive site induction, and be supervised by a competent person.

Waste Disposal

Collect in sealed heavy duty plastic bags, dispose as general solid waste unless otherwise specified, Do not burn.

Review and Monitoring

This SWMS must be reviewed if work conditions change or after any incident.