

---

```
% Given LC Values
```

```
Lf = 3e-3;
```

```
Cf = 600e-6;
```

```
R = 0.45;
```

```
L = 2e-3;
```

```
% Define Transfer Function
```

```
s = tf('s');
```

```
H = 1 / (Lf*Cf*s^2 + s*Lf/(R+s*L) + 1); % LC Filter Transfer Function
```


```
% Bode Plot
```

```
figure;
```

```
bode(H);
```

```
grid on;
```

```
title('Bode Plot of LC Filter');
```



*Published with MATLAB® R2024b*