





Size	Number	Revision
C		
Date:	11/28/2024	Sheet of


:\Altium\..\iF11M.SchDoc D



























Ground Loop may occur. in that case differential amplifier need to be introduced



need to compensate value reduced by voltage drop across the MOSFET Q2

Size	Number		Revision
C			
Date:	11/28/2024	Sheet of	•
File:	D:\Altium\\microcontroller.SchDoc	Drawn By:	