Direction "from"

Key	Value	Meaning
humidity	0 ... 100 [%], step 0.4	Rel. Humidity (linear)
temperature	-20 ... 60 [°C], step 0.32	Temperature (linear)