Direction "from"

Key	Value	Meaning
humidity	0 ... 100 [%], step 0.4	Rel. Humidity (linear)
occupancyButton	pressed	Button is pressed
	released	Button is released
temperature	0 ... 40 [°C], step 0.16	Temperature (linear)