Ip representation:D2-14-5B

IP KEY	Valid range	Step size	Unit	IP Meaning
Temperature	0...800	0.10	°C	Measurement of Temperature in linear
	801			Saturation
	802			Sensor error
	1023			Sensor not present
Barometer	0...650	0.18	hPa/ mbar	Barometer linear
	1001			Saturation
	1002			Sensor error
	1023			Sensor not present
Particle Matter 1um	0...1000	1	ug/m3	PM1
	1001			Saturation
	1002			Sensor error
	1023			Sensor not present
Particle Matter 2.5um	0...1000	1	ug/m3	PM2.5
	1001			Saturation
	1002			Sensor error
	1023			Sensor not present
Particle Matter 10um	0...1000	1	ug/m3	PM10
	1001			Saturation
	1002			Sensor error
	1023			Sensor not present
Noise_average	0...200	1	dB/dB a	Noise Average
	201			Saturation
	202			Sensor error
	255			Sensor not present
Noise_peak	0...200	1	dB/dB a	Noise Peak
	201			Saturation
	202			Sensor error
	255			Sensor not present

IP KEY	Valid range	Step size	Unit	IP Meaning
Noise_Loc	0...180	1	Degree	Noise localisation
	182			Sensor error
	255			Sensor not present
Noise_Unit	0			dB
	1			dBa
Humidity	0...100	1	%	Measurement of Relative Humidity in linear
	102			Sensor error
	127			Sensor nor present