Ip representation:D2-14-5F

IP KEY	Valid range	Step size	Unit	IP Meaning
temperature	0...200	0.50	C	Measurement of Temperature in linear
	252			Underflow error
	253			Overflow error
	254			Supported + Invalid
	255			notSupported
Illumination	0...4000	2	lx	Illumination linear in 2 lx steps
	4093			Overflow error
	4094			Supported + Invalid
	4095			notSupported
Co2	0...8000	1	ppm	CO2 linear
	8188			Sudden change error
	8189			Overflow error
	8190			Supported + Invalid
	8191			notSupported
humidity	0...100	1	%	Measurement of Relative Humidity in %
	126			Supported + Invalid
	127			notSupported