









High Current Spare Outputs PWM Idle and Boost outputs GND Spare High Current outputs 100k R28 Q_NMOS_GDSD U6 ULN2003 GND MCU-D4) 9 **(**12V-SW IDLE-OUT GND 10k R27 GND (12V-SW Stepper Idle A1 Pololu_Breakout_DRV8825 HC-05 Bluetooth Connector J2 Conn_01x06

Speeduino	
Sheet: /Outputs/	
File: outputs.sch	
Title: 0.4	
Size: A4 Date: 2021-03-27	Rev: 4d
KiCad E.D.A. kicad (5.1.9-0-10_14)	ld: 6/7

