

PROPERTY WALK — STATUS MEMO



Thirteen East

614 13th Avenue East · Capitol Hill · Seattle, WA 98112

A quiet address on Thirteenth Avenue East.

WALK DATE

Wednesday, May 20, 2026

PREPARED FOR

Ownership

PREPARED BY

Spencer Davis · Bonavista Property
Management

EXECUTIVE SUMMARY

A walk-through of 614 13th Avenue East was completed on May 20, 2026. The building is in generally good order — newly staged top-floor units are clean and photography-ready, and the lower floors remain secured. Two deficiencies require attention: a broken third-floor window with signs of attempted pry-entry, and several rooftop hazards (unmarked lip, unsecured tile, lack of leveling and drainage). One coordination item: keys to the staged top units need to be handed off to Regional.

Findings at a glance

CRITICAL Rooftop — unmarked lip, unsecured tiles, no leveling, single drain (pooling).

HIGH 3rd Floor — broken window with signs of pry-entry; vendor status unknown.

ACTION Key handoff — top staged units to Regional for marketing access.

POSITIVE New staging — top units cleaned and ready for photography.

Broken window, signs of pry-entry

HIGH PRIORITY

A window on the third floor was found broken during the walk. The frame shows clear signs of having been pried — tool marks along the sash and deformation consistent with attempted forced entry. Vendor status is unknown; it is not confirmed whether a contractor has been notified or scheduled. Every unit aside from second-floor-and-up was found locked, so unauthorized access into the building below the affected level is limited, but the breach point itself remains open.

Recommended actions

- Confirm vendor engagement and ETA on glazing repair this week.
- Board-up the opening today as an interim measure if the glazier is more than 48 hours out.
- Add an exterior security presence (camera coverage or after-hours patrol) until the window is restored.
- Walk the rest of the third-floor envelope for other pry signs not visible from the street.



Third-floor window — broken pane and visible tool marks along the sash (3 angles).

Multiple safety + drainage issues



CRITICAL — ADDRESS ASAP

Several rooftop conditions warrant immediate attention. On entering the rooftop area there is an unmarked lip at the threshold and, immediately past it, a sudden dip in the deck — both unmarked and at a height differential significant enough to cause a fall. Decking tile in this transition zone is not secured and shifts underfoot. The roof field is not leveled, which compromises any furniture or amenity placement and indicates uneven structural loading.

Drainage is single-point — only one scupper/drain was observed across the entire roof — and there is no raised decking or sleeper system to lift the walking surface off the membrane. Standing water is present and pooling against the membrane will accelerate deterioration of both the membrane and the finishes; the wet decking also presents a slip hazard on top of the existing trip hazards.

Recommended actions

- Tape off the rooftop or post a do-not-enter notice until the lip, dip, and loose tiles are remediated.
- Engage a roofing consultant this week for a written scope on: leveling, secondary drainage, raised decking / sleeper system.
- Mark the threshold lip with high-visibility nosing as an interim safety measure.
- Re-bed or replace loose tiles before any tenant-facing use of the roof resumes.



Rooftop — threshold lip and dip, unsecured tiles, pooling water against the membrane.

Newly staged & cleaned, ready for photography

ACTION — KEYS TO REGIONAL

The top-floor units have been turned, cleaned, and staged. They are ready for marketing photography. To enable Regional to access the units for shoots and tours, keys to the staged units need to be handed off to Regional.

Action item


- Provide keys for the newly staged top units to Regional this week.



Top units — staged and photography-ready (6 of 10 shown).

How we branded the building's web presence

Live site: <https://thethirteeneast.com>



thethirteeneast.com — homepage hero (live capture).

Single-page preleasing microsite built by Bonavista to turn qualified leads into scheduled tours. Aesthetic: a “speakeasy mood — ink + candlelight,” a warm near-black field with one amber candle-glow accent reserved for the tour CTA. Photography graded toward evening warmth, editorial section structure (numbered headings, brass mono labels, brass hairlines). Stack: Next.js 16 / React 19 / Tailwind v4. Footer-attributed to Bonavista Management.

Type system

- Fraunces — display serif (the “Thirteen East” wordmark, headlines).
- Inter Tight — body copy.
- IBM Plex Mono — numerals and section labels (“01 — THE BUILDING”, “614 13TH AVE E”).

PROPERTY COLOR PALETTE · 8 NAMED BRAND TOKENS

Values below are pulled verbatim from the site's design tokens (app/globals.css). Use these any time the property needs to appear in a Bonavista-managed asset.

