Solutions to Skill-Assessment Exercises

CHAPTER 2

2.1

The Laplace transform of t is $\frac{1}{s^2}$ using Table 2.1, Item 3. Using Table 2.2, Item 4,

$$F(s) = \frac{1}{\left(s+5\right)^2}.$$

2.2

Expanding F(s) by partial fractions yields:

$$F(s) = \frac{A}{s} + \frac{B}{s+2} + \frac{C}{(s+3)^2} + \frac{D}{(s+3)}$$

where,

$$A = \frac{10}{(s+2)(s+3)^2} \bigg|_{S \to 0} = \frac{5}{9} \quad B = \frac{10}{s(s+3)^2} \bigg|_{S \to -2} = -5$$

$$C = \frac{10}{s(s+2)}\Big|_{s\to -3} = \frac{10}{3}$$
, and $D = (s+3)^2 \frac{dF(s)}{ds}\Big|_{s\to -3} = \frac{40}{9}$

Taking the inverse Laplace transform yields,

$$f(t) = \frac{5}{9} - 5e^{-2t} + \frac{10}{3}te^{-3t} + \frac{40}{9}e^{-3t}$$

2.3

Taking the Laplace transform of the differential equation assuming zero initial conditions yields:

$$s^{3}C(s) + 3s^{2}C(s) + 7sC(s) + 5C(s) = s^{2}R(s) + 4sR(s) + 3R(s)$$

Collecting terms,

$$(s^3 + 3s^2 + 7s + 5)C(s) = (s^2 + 4s + 3)R(s)$$

Thus,

$$\frac{C(s)}{R(s)} = \frac{s^2 + 4s + 3}{s^3 + 3s^2 + 7s + 5}$$

$$G(s) = \frac{C(s)}{R(s)} = \frac{2s+1}{s^2+6s+2}$$

Cross multiplying yields,

$$\frac{d^2c}{dt^2} + 6\frac{dc}{dt} + 2c = 2\frac{dr}{dt} + r$$

2.5

$$C(s) = R(s)G(s) = \frac{1}{s^2} * \frac{s}{(s+4)(s+8)} = \frac{1}{s(s+4)(s+8)} = \frac{A}{s} + \frac{B}{(s+4)} + \frac{C}{(s+8)}$$

where

$$A = \frac{1}{(s+4)(s+8)}\Big|_{s\to 0} = \frac{1}{32}$$
 $B = \frac{1}{s(s+8)}\Big|_{s\to -4} = -\frac{1}{16}$, and $C = \frac{1}{s(s+4)}\Big|_{s\to -8} = \frac{1}{32}$


Thus,

$$c(t) = \frac{1}{32} - \frac{1}{16}e^{-4t} + \frac{1}{32}e^{-8t}$$

2.6

Mesh Analysis

Transforming the network yields,



Now, writing the mesh equations,

$$\begin{array}{l} (s+1)I_1(s) - sI_2(s) - I_3(s) = V(s) \\ - sI_1(s) + (2s+1)I_2(s) - I_3(s) = 0 \\ - I_1(s) - I_2(s) + (s+2)I_3(s) = 0 \end{array}$$

Solving the mesh equations for $I_2(s)$,

$$I_2(s) = \frac{\begin{vmatrix} (s+1) & V(s) & -1 \\ -s & 0 & -1 \\ -1 & 0 & (s+2) \end{vmatrix}}{\begin{vmatrix} (s+1) & -s & -1 \\ -s & (2s+1) & -1 \\ -1 & -1 & (s+2) \end{vmatrix}} = \frac{(s^2 + 2s + 1)V(s)}{s(s^2 + 5s + 2)}$$

But, $V_L(s) = sI_2(s)$ Hence,

$$V_L(s) = \frac{(s^2 + 2s + 1)V(s)}{(s^2 + 5s + 2)}$$

or

$$\frac{V_L(s)}{V(s)} = \frac{s^2 + 2s + 1}{s^2 + 5s + 2}$$

Nodal Analysis

Writing the nodal equations,

$$\left(\frac{1}{s} + 2\right)V_1(s) - V_L(s) = V(s)$$
$$-V_1(s) + \left(\frac{2}{s} + 1\right)V_L(s) = \frac{1}{s}V(s)$$

Solving for $V_L(s)$,

$$V_L(s) = \frac{\begin{vmatrix} \left(\frac{1}{s} + 2\right) & V(s) \\ -1 & \frac{1}{s}V(s) \end{vmatrix}}{\begin{vmatrix} \left(\frac{1}{s} + 2\right) & -1 \\ -1 & \left(\frac{2}{s} + 1\right) \end{vmatrix}} = \frac{\left(s^2 + 2s + 1\right)V(s)}{(s^2 + 5s + 2)}$$

or

$$\frac{V_L(s)}{V(s)} = \frac{s^2 + 2s + 1}{s^2 + 5s + 2}$$

2.7

Inverting

$$G(s) = -\frac{Z_2(s)}{Z_1(s)} = \frac{-100000}{\left(10^5/s\right)} = -s$$

Noninverting

$$G(s) = \frac{[Z_1(s) + Z(s)]}{Z_1(s)} = \frac{\left(\frac{10^5}{s} + 10^5\right)}{\left(\frac{10^5}{s}\right)} = s + 1$$

2.8

Writing the equations of motion,

$$(s^2 + 3s + 1)X_1(s) - (3s + 1)X_2(s) = F(s)$$
$$-(3s + 1)X_1(s) + (s^2 + 4s + 1)X_2(s) = 0$$

Solving for $X_2(s)$,

$$X_2(s) = \frac{\begin{vmatrix} (s^2 + 3s + 1) & F(s) \\ -(3s + 1) & 0 \end{vmatrix}}{\begin{vmatrix} (s^2 + 3s + 1) & -(3s + 1) \\ -(3s + 1) & (s^2 + 4s + 1) \end{vmatrix}} = \frac{(3s + 1)F(s)}{s(s^3 + 7s^2 + 5s + 1)}$$

Hence,

$$\frac{X_2(s)}{F(s)} = \frac{(3s+1)}{s(s^3+7s^2+5s+1)}$$

2.9

Writing the equations of motion,

$$(s^2 + s + 1)\theta_1(s) - (s + 1)\theta_2(s) = T(s)$$
$$-(s + 1)\theta_1(s) + (2s + 2)\theta_2(s) = 0$$

where $\theta_1(s)$ is the angular displacement of the inertia. Solving for $\theta_2(s)$,


$$\theta_2(s) = \frac{\begin{vmatrix} \left(s^2 + s + 1\right) & T(s) \\ -(s+1) & 0 \end{vmatrix}}{\begin{vmatrix} \left(s^2 + s + 1\right) & -(s+1) \\ -(s+1) & (2s+2) \end{vmatrix}} = \frac{(s+1)T(s)}{2s^3 + 3s^2 + 2s + 1}$$

From which, after simplification,

$$G(s) = \frac{\theta_2(s)}{T(s)} = \frac{1}{2s^2 + s + 1}$$

2.10

Transforming the network to one without gears by reflecting the 4 N-m/rad spring to the left and multiplying by $(25/50)^2$, we obtain,



Writing the equations of motion,

$$(s^2 + s)\theta_1(s) - s\theta_a(s) = T(s)$$
$$-s\theta_1(s) + (s+1)\theta_a(s) = 0$$

where $\theta_1(s)$ is the angular displacement of the 1-kg inertia. Solving for $\theta_a(s)$,

$$\theta_a(s) = \frac{\begin{vmatrix} (s^2 + s) & T(s) \\ -s & 0 \end{vmatrix}}{\begin{vmatrix} (s^2 + s) & -s \\ -s & (s+1) \end{vmatrix}} = \frac{sT(s)}{s^3 + s^2 + s}$$

From which,

$$\frac{\theta_a(s)}{T(s)} = \frac{1}{s^2 + s + 1}$$

But,
$$\theta_2(s) = \frac{1}{2}\theta_a(s)$$
.

Thus,

$$\frac{\theta_2(s)}{T(s)} = \frac{1/2}{s^2 + s + 1}$$

2.11

First find the mechanical constants.

$$J_m = J_a + J_L \left(\frac{1}{5} * \frac{1}{4}\right)^2 = 1 + 400 \left(\frac{1}{400}\right) = 2$$
$$D_m = D_a + D_L \left(\frac{1}{5} * \frac{1}{4}\right)^2 = 5 + 800 \left(\frac{1}{400}\right) = 7$$

Now find the electrical constants. From the torque-speed equation, set $\omega_{\rm m}=0$ to find stall torque and set $T_m=0$ to find no-load speed. Hence,

$$T_{stall} = 200$$

 $\omega_{no-load} = 25$

which,

$$\frac{K_t}{R_a} = \frac{T_{stall}}{E_a} = \frac{200}{100} = 2$$

$$K_b = \frac{E_a}{\omega_{no-load}} = \frac{100}{25} = 4$$

Substituting all values into the motor transfer function,

$$\frac{\theta_m(s)}{E_a(s)} = \frac{\frac{K_T}{R_a J_m}}{s\left(s + \frac{1}{J_m}\right)\left(D_m + \frac{K_T K_b}{R_a}\right)} = \frac{1}{s\left(s + \frac{15}{2}\right)}$$

where $\theta_m(s)$ is the angular displacement of the armature.

Now
$$\theta_L(s) = \frac{1}{20} \theta_m(s)$$
. Thus,

$$\frac{\theta_L(s)}{E_a(s)} = \frac{1/20}{s\left(s + \frac{15}{2}\right)}$$

2.12

Letting


$$\theta_1(s) = \omega_1(s)/s$$

 $\theta_2(s) = \omega_2(s)/s$

in Eqs. 2.127, we obtain


$$\left(J_1s + D_1 + \frac{K}{s}\right)\omega_1(s) - \frac{K}{s}\omega_2(s) = T(s)$$
$$-\frac{K}{s}\omega_1(s) + \left(J_2s + D_2 + \frac{K}{s}\right)\omega_2(s)$$

From these equations we can draw both series and parallel analogs by considering these to be mesh or nodal equations, respectively.



Series analog

Parallel analog



2.13

Writing the nodal equation,

$$C\frac{dv}{dt} + i_r - 2 = i(t)$$

But,

$$C = 1$$

$$v = v_o + \delta v$$

$$i_r = e^{v_r} = e^v = e^{v_o + \delta v}$$

Substituting these relationships into the differential equation,

$$\frac{d(\nu_o + \delta \nu)}{dt} + e^{\nu_o + \delta \nu} - 2 = i(t) \tag{1}$$

We now linearize e^{v} .

The general form is

$$f(v) - f(v_o) \approx \frac{df}{dv} \Big|_{v_o} \delta v$$

Substituting the function, $f(v) = e^v$, with $v = v_o + \delta v$ yields,

$$e^{v_o + \delta v} - e^{v_o} \approx \frac{de^v}{dv} \bigg|_{v_o} \delta v$$

Solving for $e^{v_o + \delta v}$,

$$e^{v_o + \delta v} = e^{v_o} + \frac{de^v}{dv} \bigg|_{v_o} \delta v = e^{v_o} + e^{v_o} \delta v$$

Substituting into Eq. (1)

$$\frac{d\delta v}{dt} + e^{v_o} + e^{v_o} \delta v - 2 = i(t) \tag{2}$$

Setting i(t) = 0 and letting the circuit reach steady state, the capacitor acts like an open circuit. Thus, $v_o = v_r$ with $i_r = 2$. But, $i_r = e^{v_r}$ or $v_r = \ln i_r$.

Hence, $v_o = \ln 2 = 0.693$. Substituting this value of v_o into Eq. (2) yields

$$\frac{d\delta v}{dt} + 2\delta v = i(t)$$

Taking the Laplace transform,

$$(s+2)\delta v(s) = I(s)$$

Solving for the transfer function, we obtain

$$\frac{\delta v(s)}{I(s)} = \frac{1}{s+2}$$


or

$$\frac{V(s)}{I(s)} = \frac{1}{s+2}$$
 about equilibrium.

CHAPTER 3

3.1

Identifying appropriate variables on the circuit yields



Writing the derivative relations

$$C_1 \frac{dv_{C_1}}{dt} = i_{C_1}$$

$$L \frac{di_L}{dt} = v_L$$

$$C_2 \frac{dv_{C_2}}{dt} = i_{C_2}$$
(1)

Using Kirchhoff's current and voltage laws,

$$i_{C_1} = i_L + i_R = i_L + \frac{1}{R}(v_L - v_{C_2})$$

 $v_L = -v_{C_1} + v_i$
 $i_{C_2} = i_R = \frac{1}{R}(v_L - v_{C_2})$

Substituting these relationships into Eqs. (1) and simplifying yields the state equations as

$$\frac{dv_{C_1}}{dt} = -\frac{1}{RC_1}v_{C_1} + \frac{1}{C_1}i_L - \frac{1}{RC_1}v_{C_2} + \frac{1}{RC_1}v_i$$

$$\frac{di_L}{dt} = -\frac{1}{L}v_{C_1} + \frac{1}{L}v_i$$

$$\frac{dv_{C_2}}{dt} = -\frac{1}{RC_2}v_{C_1} - \frac{1}{RC_2}v_{C_2} + \frac{1}{RC_2}v_i$$

where the output equation is

$$v_o = v_{C_2}$$

Putting the equations in vector-matrix form,

$$\dot{\mathbf{x}} = \begin{bmatrix} -\frac{1}{RC_1} & \frac{1}{C_1} & -\frac{1}{RC_1} \\ -\frac{1}{L} & 0 & 0 \\ -\frac{1}{RC_2} & 0 & -\frac{1}{RC_2} \end{bmatrix} \mathbf{x} + \begin{bmatrix} \frac{1}{RC_1} \\ \frac{1}{L} \\ \frac{1}{RC_2} \end{bmatrix} v_i(t)$$
$$y = \begin{bmatrix} 0 & 0 & 1 \end{bmatrix} \mathbf{x}$$

3.2

Writing the equations of motion

$$(s^{2} + s + 1)X_{1}(s) - sX_{2}(s) = F(s)$$

$$-sX_{1}(s) + (s^{2} + s + 1)X_{2}(s) - X_{3}(s) = 0$$

$$-X_{2}(s) + (s^{2} + s + 1)X_{3}(s) = 0$$

Taking the inverse Laplace transform and simplifying,

$$\begin{split} \ddot{x}_1 &= -\dot{x}_1 - x_1 + \dot{x}_2 + f \\ \ddot{x}_2 &= \dot{x}_1 - \dot{x}_2 - x_2 + x_3 \\ \ddot{x}_3 &= -\dot{x}_3 - x_3 + x_2 \end{split}$$

Defining state variables, z_i ,

$$z_1 = x_1; z_2 = \dot{x}_1; z_3 = x_2; z_4 = \dot{x}_2; z_5 = x_3; z_6 = \dot{x}_3$$

Writing the state equations using the definition of the state variables and the inverse transform of the differential equation,

$$\dot{z}_1 = z_2
\dot{z}_2 = \ddot{x}_1 = -\dot{x}_1 - x_1 + \dot{x}_2 + f = -z_2 - z_1 + z_4 + f
\dot{z}_3 = \dot{x}_2 = z_4
\dot{z}_4 = \ddot{x}_2 = \dot{x}_1 - \dot{x}_2 - x_2 + x_3 = z_2 - z_4 - z_3 + z_5
\dot{z}_5 = \dot{x}_3 = z_6
\dot{z}_6 = \ddot{x}_3 = -\dot{x}_3 - x_3 + x_2 = -z_6 - z_5 + z_3$$

The output is z_5 . Hence, $y = z_5$. In vector-matrix form,

$$\dot{\mathbf{z}} = \begin{bmatrix} 0 & 1 & 0 & 0 & 0 & 0 \\ -1 & -1 & 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 1 & 0 & 0 \\ 0 & 1 & -1 & -1 & 1 & 0 \\ 0 & 0 & 0 & 0 & 0 & 1 \\ 0 & 0 & 1 & 0 & -1 & -1 \end{bmatrix} \mathbf{z} + \begin{bmatrix} 0 \\ 1 \\ 0 \\ 0 \\ 0 \\ 0 \end{bmatrix} f(t); y = \begin{bmatrix} 0 & 0 & 0 & 0 & 1 & 0 \end{bmatrix} \mathbf{z}$$

3.3

First derive the state equations for the transfer function without zeros.

$$\frac{X(s)}{R(s)} = \frac{1}{s^2 + 7s + 9}$$

Cross multiplying yields

$$(s^2 + 7s + 9)X(s) = R(s)$$

Taking the inverse Laplace transform assuming zero initial conditions, we get

$$\ddot{x} + 7\dot{x} + 9x = r$$

Defining the state variables as,

$$x_1 = x$$
$$x_2 = \dot{x}$$

Hence,

$$\dot{x}_1 = x_2$$

 $\dot{x}_2 = \ddot{x} = -7\dot{x} - 9x + r = -9x_1 - 7x_2 + r$

Using the zeros of the transfer function, we find the output equation to be,

$$c = 2\dot{x} + x = x_1 + 2x_2$$

Putting all equation in vector-matrix form yields,

$$\dot{\mathbf{x}} = \begin{bmatrix} 0 & 1 \\ -9 & -7 \end{bmatrix} \mathbf{x} + \begin{bmatrix} 0 \\ 1 \end{bmatrix} r$$

$$c = \begin{bmatrix} 1 & 2 \end{bmatrix} \mathbf{x}$$

The state equation is converted to a transfer function using

$$G(s) = \mathbf{C}(s\mathbf{I} - \mathbf{A})^{-1}\mathbf{B} \tag{1}$$

where

$$\mathbf{A} = \begin{bmatrix} -4 & -1.5 \\ 4 & 0 \end{bmatrix}, \mathbf{B} = \begin{bmatrix} 2 \\ 0 \end{bmatrix}, \text{ and } \mathbf{C} = \begin{bmatrix} 1.5 & 0.625 \end{bmatrix}.$$

Evaluating $(s\mathbf{I} - \mathbf{A})$ yields

$$(s\mathbf{I} - \mathbf{A}) = \begin{bmatrix} s+4 & 1.5 \\ -4 & s \end{bmatrix}$$

Taking the inverse we obtain

$$(s\mathbf{I} - \mathbf{A})^{-1} = \frac{1}{s^2 + 4s + 6} \begin{bmatrix} s & -1.5 \\ 4 & s + 4 \end{bmatrix}$$

Substituting all expressions into Eq. (1) yields

$$G(s) = \frac{3s+5}{s^2+4s+6}$$

3.5

Writing the differential equation we obtain

$$\frac{d^2x}{dt^2} + 2x^2 = 10 + \delta f(t) \tag{1}$$

Letting $x = x_o + \delta x$ and substituting into Eq. (1) yields

$$\frac{d^2(x_o + \delta x)}{dt^2} + 2(x_o + \delta x)^2 = 10 + \delta f(t)$$
 (2)

Now, linearize x^2 .

$$(x_o + \delta x)^2 - x_o^2 = \frac{d(x^2)}{dx} \bigg|_{x} \delta x = 2x_o \delta x$$

from which

$$(x_o + \delta x)^2 = x_o^2 + 2x_o \delta x \tag{3}$$

Substituting Eq. (3) into Eq. (1) and performing the indicated differentiation gives us the linearized intermediate differential equation,

$$\frac{d^2 \delta x}{dt^2} + 4x_o \delta x = -2x_o^2 + 10 + \delta f(t) \tag{4}$$

The force of the spring at equilibrium is 10 N. Thus, since $F = 2x^2$, $10 = 2x_o^2$ from which

$$x_o = \sqrt{5}$$

Substituting this value of x_o into Eq. (4) gives us the final linearized differential equation.

$$\frac{d^2\delta x}{dt^2} + 4\sqrt{5}\,\delta x = \delta f(t)$$

Selecting the state variables,

$$x_1 = \delta x$$
$$x_2 = \dot{\delta} x$$

Writing the state and output equations

$$\dot{x}_1 = x_2$$

$$\dot{x}_2 = \ddot{\delta}x = -4\sqrt{5}x_1 + \delta f(t)$$

$$v = x_1$$

Converting to vector-matrix form yields the final result as

$$\dot{\mathbf{x}} = \begin{bmatrix} 0 & 1 \\ -4\sqrt{5} & 0 \end{bmatrix} \mathbf{x} + \begin{bmatrix} 0 \\ 1 \end{bmatrix} \delta f(t)$$
$$\mathbf{y} = \begin{bmatrix} 1 & 0 \end{bmatrix} \mathbf{x}$$

CHAPTER 4

4.1

For a step input

$$C(s) = \frac{10(s+4)(s+6)}{s(s+1)(s+7)(s+8)(s+10)} = \frac{A}{s} + \frac{B}{s+1} + \frac{C}{s+7} + \frac{D}{s+8} + \frac{E}{s+10}$$

Taking the inverse Laplace transform,

$$c(t) = A + Be^{-t} + Ce^{-7t} + De^{-8t} + Ee^{-10t}$$

4.2

Since
$$a = 50$$
, $T_c = \frac{1}{a} = \frac{1}{50} = 0.02$ s; $T_s = \frac{4}{a} = \frac{4}{50} = 0.08$ s; and $T_r = \frac{2.2}{a} = \frac{2.2}{50} = 0.044$ s.

4.3

- **a.** Since poles are at $-6 \pm i \, 19.08$, $c(t) = A + Be^{-6t} \cos(19.08t + \phi)$.
- **b.** Since poles are at -78.54 and -11.46, $c(t) = A + Be^{-78.54t} + Ce^{-11.4t}$.
- **c.** Since poles are double on the real axis at $-15 c(t) = A + Be^{-15t} + Cte^{-15t}$.
- **d.** Since poles are at $\pm j 25$, $c(t) = A + B \cos(25t + \phi)$.

4.4

- **a.** $\omega_n = \sqrt{400} = 20$ and $2\zeta\omega_n = 12$; $\therefore \zeta = 0.3$ and system is underdamped.
- **b.** $\omega_n = \sqrt{900} = 30$ and $2\zeta\omega_n = 90$; $\zeta = 1.5$ and system is overdamped.
- **c.** $\omega_n = \sqrt{225} = 15$ and $2\zeta\omega_n = 30$; $\therefore \zeta = 1$ and system is critically damped.
- **d.** $\omega_n = \sqrt{625} = 25$ and $2\zeta\omega_n = 0$; $\zeta = 0$ and system is undamped.

$$\omega_n = \sqrt{361} = 19 \text{ and } 2\zeta\omega_n = 16; \quad \therefore \zeta = 0.421.$$

Now,
$$T_s = \frac{4}{\zeta \omega_n} = 0.5 s$$
 and $T_p = \frac{\pi}{\omega_n \sqrt{1 - \zeta^2}} = 0.182 s$.

From Figure 4.16, $\omega_n T_r = 1.4998$. Therefore, $T_r = 0.079$ s.

Finally,
$$\%$$
os = $e^{\frac{-\zeta\pi}{\sqrt{1}-\zeta^2}} * 100 = 23.3\%$

4.6

- **a.** The second-order approximation is valid, since the dominant poles have a real part of -2 and the higher-order pole is at -15, i.e. more than five-times further.
- **b.** The second-order approximation is not valid, since the dominant poles have a real part of -1 and the higher-order pole is at -4, i.e. not more than five-times further.

4.7

- **a.** Expanding $\frac{1}{s}$ G(s) by partial fractions yields $G(s) = \frac{1}{s} + \frac{0.8942}{s+20} \frac{1.5918}{s+10} \frac{0.3023}{s+6.5}$. But -0.3023 is not an order of magnitude less than residues of second-order terms (term 2 and 3). Therefore, a second-order approximation is not valid.
- **b.** Expanding $\frac{1}{s}G(s)$ by partial fractions yields $G(s) = \frac{1}{s} + \frac{0.9782}{s+20} \frac{1.9078}{s+10} \frac{0.0704}{s+6.5}$. Because 0.0704 is an order of magnitude less than residues of second-order terms (term 2 and 3). Therefore, a second-order approximation is valid.

4.8

See Figure 4.31 in the textbook for the Simulink block diagram and the output responses.

4.9

a. Since
$$s\mathbf{I} - \mathbf{A} = \begin{bmatrix} s & -2 \\ 3 & s+5 \end{bmatrix}$$
, $(s\mathbf{I} - \mathbf{A})^{-1} = \frac{1}{s^2 + 5s + 6} \begin{bmatrix} s+5 & 2 \\ -3 & s \end{bmatrix}$. Also, $\mathbf{BU}(s) = \begin{bmatrix} 0 \\ 1/(s+1) \end{bmatrix}$.

The state vector is $\mathbf{X}(s) = (s\mathbf{I} - \mathbf{A})^{-1}[\mathbf{x}(0) + \mathbf{B}\mathbf{U}(s)] = \frac{1}{(s+1)(s+2)(s+3)} \times \left[\frac{2(s^2 + 7s + 7)}{s^2 - 4s - 6} \right]$. The output is $Y(s) = [1 \ 3]\mathbf{X}(s) = \frac{5s^2 + 2s - 4}{(s+1)(s+2)(s+3)} = \frac{0.5}{s+1} - \frac{12}{s+2} + \frac{17.5}{s+3}$. Taking the inverse Laplace transform yields $y(t) = -0.5e^{-t} - 12e^{-2t} + 17.5e^{-3t}$.

b. The eigenvalues are given by the roots of $|s\mathbf{I} - \mathbf{A}| = s^2 + 5s + 6$, or -2 and -3.

4.10

a. Since $(s\mathbf{I} - \mathbf{A}) = \begin{bmatrix} s & -2 \\ 2 & s+5 \end{bmatrix}$, $(s\mathbf{I} - \mathbf{A})^{-1} = \frac{1}{s^2 + 5s + 4} \begin{bmatrix} s+5 & 2 \\ -2 & s \end{bmatrix}$. Taking the Laplace transform of each term, the state transition matrix is given by

$$\Phi(t) = \begin{bmatrix} \frac{4}{3}e^{-t} - \frac{1}{3}e^{-4t} & \frac{2}{3}e^{-t} - \frac{2}{3}e^{-4t} \\ -\frac{2}{3}e^{-t} + \frac{2}{3}e^{-4t} & -\frac{1}{3}e^{-t} + \frac{4}{3}e^{-4t} \end{bmatrix}.$$

b. Since
$$\Phi(t-\tau) = \begin{bmatrix} \frac{4}{3}e^{-(t-\tau)} - \frac{1}{3}e^{-4(t-\tau)} & \frac{2}{3}e^{-(t-\tau)} - \frac{2}{3}e^{-4(t-\tau)} \\ -\frac{2}{3}e^{-(t-\tau)} + \frac{2}{3}e^{-4(t-\tau)} & -\frac{1}{3}e^{-(t-\tau)} + \frac{4}{3}e^{-4(t-\tau)} \end{bmatrix}$$
 and
$$\mathbf{B}\mathbf{u}(\tau) = \begin{bmatrix} 0 \\ e^{-2\tau} \end{bmatrix}, \ \Phi(t-\tau)\mathbf{B}\mathbf{u}(\tau) = \begin{bmatrix} \frac{2}{3}e^{-\tau}e^{-t} - \frac{2}{3}e^{2\tau}e^{-4t} \\ -\frac{1}{3}e^{-\tau}e^{-t} + \frac{4}{3}e^{2\tau}e^{-4t} \end{bmatrix}.$$
 Thus, $\mathbf{x}(t) = \Phi(t)\mathbf{x}(0) + \int_0^t \Phi(t-\tau)$


$$\mathbf{BU}(\tau)d\tau = \begin{bmatrix} \frac{10}{3}e^{-t} - e^{-2t} - \frac{4}{3}e^{-4t} \\ -\frac{5}{3}e^{-t} + e^{-2t} + \frac{8}{3}e^{-4t} \end{bmatrix}$$

c.
$$y(t) = \begin{bmatrix} 2 & 1 \end{bmatrix} \mathbf{x} = 5e^{-t} - e^{-2t}$$

CHAPTER 5

5.1

Combine the parallel blocks in the forward path. Then, push $\frac{1}{s}$ to the left past the pickoff point.




Combine the parallel feedback paths and get 2s. Then, apply the feedback formula, simplify, and get, $T(s) = \frac{s^3 + 1}{2s^4 + s^2 + 2s}$.

5.2


Find the closed-loop transfer function, $T(s) = \frac{G(s)}{1 + G(s)H(s)} = \frac{16}{s^2 + as + 16}$, where and $G(s) = \frac{16}{s(s+a)}$ and H(s) = 1. Thus, $\omega_n = 4$ and $2\zeta\omega_n = a$, from which $\zeta = \frac{a}{8}$. But, for 5% overshoot, $\zeta = \frac{-\ln\left(\frac{\%}{100}\right)}{\sqrt{\pi^2 + \ln^2\left(\frac{\%}{100}\right)}} = 0.69$. Since, $\zeta = \frac{a}{8}$, a = 5.52.

5.3


Label nodes.




Draw nodes.



Connect nodes and label subsystems.



Eliminate unnecessary nodes.



Forward-path gains are $G_1G_2G_3$ and G_1G_3 . Loop gains are $-G_1G_2H_1, -G_2H_2,$ and $-G_3H_3$. Nontouching loops are $[-G_1G_2H_1][-G_3H_3] = G_1G_2G_3H_1H_3$ and $[-G_2H_2][-G_3H_3] = G_2G_3H_2H_3$. Also, $\Delta = 1 + G_1G_2H_1 + G_2H_2 + G_3H_3 + G_1G_2G_3H_1H_3 + G_2G_3H_2H_3$. Finally, $\Delta_1 = 1$ and $\Delta_2 = 1$.

Substituting these values into $T(s) = \frac{C(s)}{R(s)} = \frac{\sum_{k} T_k \Delta_k}{\Delta}$ yields


$$T(s) = \frac{G_1(s)G_3(s)[1 + G_2(s)]}{[1 + G_2(s)H_2(s) + G_1(s)G_2(s)H_1(s)][1 + G_3(s)H_3(s)]}$$

5.5

The state equations are,


$$\dot{x}_1 = -2x_1 + x_2
\dot{x}_2 = -3x_2 + x_3
\dot{x}_3 = -3x_1 - 4x_2 - 5x_3 + r
y = x_2$$

Drawing the signal-flow diagram from the state equations yields



5.6

From $G(s) = \frac{100(s+5)}{s^2+5s+6}$ we draw the signal-flow graph in controller canonical form and add the feedback.



Writing the state equations from the signal-flow diagram, we obtain

$$\mathbf{x} = \begin{bmatrix} -105 & -506 \\ 1 & 0 \end{bmatrix} \mathbf{x} + \begin{bmatrix} 1 \\ 0 \end{bmatrix} r$$
$$y = \begin{bmatrix} 100 & 500 \end{bmatrix} \mathbf{x}$$

5.7

From the transformation equations,

$$\mathbf{P}^{-1} = \begin{bmatrix} 3 & -2 \\ 1 & -4 \end{bmatrix}$$

Taking the inverse,

$$\mathbf{P} = \begin{bmatrix} 0.4 & -0.2 \\ 0.1 & -0.3 \end{bmatrix}$$

Now,

$$\mathbf{P}^{-1}\mathbf{A}\mathbf{P} = \begin{bmatrix} 3 & -2 \\ 1 & -4 \end{bmatrix} \begin{bmatrix} 1 & 3 \\ -4 & -6 \end{bmatrix} \begin{bmatrix} 0.4 & -0.2 \\ 0.1 & -0.3 \end{bmatrix} = \begin{bmatrix} 6.5 & -8.5 \\ 9.5 & -11.5 \end{bmatrix}$$

$$\mathbf{P}^{-1}\mathbf{B} = \begin{bmatrix} 3 & -2 \\ 1 & -4 \end{bmatrix} \begin{bmatrix} 1 \\ 3 \end{bmatrix} = \begin{bmatrix} -3 \\ -11 \end{bmatrix}$$

$$\mathbf{C}\mathbf{P} = \begin{bmatrix} 1 & 4 \end{bmatrix} \begin{bmatrix} 0.4 & -0.2 \\ 0.1 & -0.3 \end{bmatrix} = \begin{bmatrix} 0.8 & -1.4 \end{bmatrix}$$

Therefore,

$$\dot{\mathbf{z}} = \begin{bmatrix} 6.5 & -8.5 \\ 9.5 & -11.5 \end{bmatrix} \mathbf{z} + \begin{bmatrix} -3 \\ -11 \end{bmatrix} u$$
$$y = \begin{bmatrix} 0.8 & -1.4 \end{bmatrix} \mathbf{z}$$

5.8

First find the eigenvalues.

$$|\lambda \mathbf{I} - \mathbf{A}| = \begin{vmatrix} \begin{bmatrix} \lambda & 0 \\ 0 & \lambda \end{bmatrix} - \begin{bmatrix} 1 & 3 \\ -4 & -6 \end{bmatrix} = \begin{vmatrix} \lambda - 1 & -3 \\ 4 & \lambda + 6 \end{vmatrix} = \lambda^2 + 5\lambda + 6$$

From which the eigenvalues are -2 and -3.

Now use $\mathbf{A}x_i = \lambda x_i$ for each eigenvalue, λ . Thus,

$$\begin{bmatrix} 1 & 3 \\ -4 & -6 \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \end{bmatrix} = \lambda \begin{bmatrix} x_1 \\ x_2 \end{bmatrix}$$

For $\lambda = -2$,

$$3x_1 + 3x_2 = 0$$

$$-4x_1 - 4x_2 = 0$$

Thus $x_1 = -x_2$ For $\lambda = -3$

$$4x_1 + 3x_2 = 0$$

$$-4x_1 - 3x_2 = 0$$

Thus $x_1 = -x_2$ and $x_1 = -0.75x_2$; from which we let

$$\mathbf{P} = \begin{bmatrix} 0.707 & -0.6 \\ -0.707 & 0.8 \end{bmatrix}$$

Taking the inverse yields

$$\mathbf{P}^{-1} = \begin{bmatrix} 5.6577 & 4.2433 \\ 5 & 5 \end{bmatrix}$$

Hence.

$$\mathbf{D} = \mathbf{P}^{-1}\mathbf{A}\mathbf{P} = \begin{bmatrix} 5.6577 & 4.2433 \\ 5 & 5 \end{bmatrix} \begin{bmatrix} 1 & 3 \\ -4 & -6 \end{bmatrix} \begin{bmatrix} 0.707 & -0.6 \\ -0.707 & 0.8 \end{bmatrix} = \begin{bmatrix} -2 & 0 \\ 0 & -3 \end{bmatrix}$$

$$\mathbf{P}^{-1}\mathbf{B} = \begin{bmatrix} 5.6577 & 4.2433 \\ 5 & 5 \end{bmatrix} \begin{bmatrix} 1 \\ 3 \end{bmatrix} = \begin{bmatrix} 18.39 \\ 20 \end{bmatrix}$$

$$\mathbf{CP} = \begin{bmatrix} 1 & 4 \end{bmatrix} \begin{bmatrix} 0.707 & -0.6 \\ -0.707 & 0.8 \end{bmatrix} = \begin{bmatrix} -2.121 & 2.6 \end{bmatrix}$$

Finally,

$$\dot{\mathbf{z}} = \begin{bmatrix} -2 & 0 \\ 0 & -3 \end{bmatrix} \mathbf{z} + \begin{bmatrix} 18.39 \\ 20 \end{bmatrix} u$$
$$\mathbf{y} = \begin{bmatrix} -2.121 & 2.6 \end{bmatrix} \mathbf{z}$$

CHAPTER 6

6.1 Make a Routh table.

.7	2	6	7	2
S	3	6	/	Z
s^6	9	4	8	6
s^5	4.666666667	4.333333333	0	0
s^4	-4.35714286	8	6	0
s^3	12.90163934	6.426229508	0	0
s^2	10.17026684	6	0	0
s^1	-1.18515742	0	0	0
s^0	6	0	0	0

Since there are four sign changes and no complete row of zeros, there are four right half-plane poles and three left half-plane poles.

6.2

Make a Routh table. We encounter a row of zeros on the s^3 row. The even polynomial is contained in the previous row as $-6s^4 + 0s^2 + 6$. Taking the derivative yields

 $-24s^3 + 0s$. Replacing the row of zeros with the coefficients of the derivative yields the s^3 row. We also encounter a zero in the first column at the s^2 row. We replace the zero with ε and continue the table. The final result is shown now as

s^6	1	-6	-1	6	
s^5	1	0	-1	0	
s^4	-6	0	6	0	
s^3	-24	0	0	0	ROZ
s^2	3	6	0	0	
s^1	$144/\epsilon$	0	0	0	
s^0	6	0	0	0	

There is one sign change below the even polynomial. Thus the even polynomial (4th order) has one right half-plane pole, one left half-plane pole, and 2 imaginary axis poles. From the top of the table down to the even polynomial yields one sign change. Thus, the rest of the polynomial has one right half-plane root, and one left half-plane root. The total for the system is two right half-plane poles, two left half-plane poles, and 2 imaginary poles.

6.3

Since
$$G(s) = \frac{K(s+20)}{s(s+2)(s+3)}$$
, $T(s) = \frac{G(s)}{1+G(s)} = \frac{K(s+20)}{s^3+5s^2+(6+K)s+20K}$

Form the Routh table.

s^3	1	(6 + K)
s^2	5	20 <i>K</i>
s^1	$\frac{30-15K}{5}$	
s^0	20K	

From the s^1 row, K < 2. From the s^0 row, K > 0. Thus, for stability, 0 < K < 2.

6.4

First find

$$|s\mathbf{I} - \mathbf{A}| = \begin{vmatrix} \begin{bmatrix} s & 0 & 0 \\ 0 & s & 0 \\ 0 & 0 & s \end{bmatrix} - \begin{bmatrix} 2 & 1 & 1 \\ 1 & 7 & 1 \\ -3 & 4 & -5 \end{bmatrix} = \begin{vmatrix} (s-2) & -1 & -1 \\ -1 & (s-7) & -1 \\ 3 & -4 & (s+5) \end{vmatrix}$$
$$= s^3 - 4s^2 - 33s + 51$$

Now form the Routh table.

s^3	1	-33
s^2	-4	51
s^1	-20.25	
s^0	51	

There are two sign changes. Thus, there are two rhp poles and one lhp pole.

CHAPTER 7

7.1

a. First check stability.

$$T(s) = \frac{G(s)}{1 + G(s)} = \frac{10s^2 + 500s + 6000}{s^3 + 70s^2 + 1375s + 6000} = \frac{10(s + 30)(s + 20)}{(s + 26.03)(s + 37.89)(s + 6.085)}$$

Poles are in the lhp. Therefore, the system is stable. Stability also could be checked via Routh-Hurwitz using the denominator of T(s). Thus,

$$15u(t): e_{step}(\infty) = \frac{15}{1 + \lim_{s \to 0} G(s)} = \frac{15}{1 + \infty} = 0$$

$$15tu(t): e_{ramp}(\infty) = \frac{15}{\lim_{s \to 0} sG(s)} = \frac{15}{\frac{10^* 20^* 30}{25^* 35}} = 2.1875$$

$$15t^2 u(t): e_{parabola}(\infty) = \frac{15}{\lim_{s \to 0} s^2 G(s)} = \frac{30}{0} = \infty, \text{ since } L[15t^2] = \frac{30}{s^3}$$

b. First check stability.

$$T(s) = \frac{G(s)}{1 + G(s)} = \frac{10s^2 + 500s + 6000}{s^5 + 110s^4 + 3875s^3 + 4.37e04s^2 + 500s + 6000}$$
$$= \frac{10(s + 30)(s + 20)}{(s + 50.01)(s + 35)(s + 25)(s^2 - 7.189e - 04s + 0.1372)}$$

From the second-order term in the denominator, we see that the system is unstable. Instability could also be determined using the Routh-Hurwitz criteria on the denominator of T(s). Since the system is unstable, calculations about steady-state error cannot be made.

7.2

a. The system is stable, since

$$T(s) = \frac{G(s)}{1 + G(s)} = \frac{1000(s+8)}{(s+9)(s+7) + 1000(s+8)} = \frac{1000(s+8)}{s^2 + 1016s + 8063}$$

and is of Type 0. Therefore,

$$K_p = \lim_{s \to 0} G(s) = \frac{1000^* 8}{7^* 9} = 127; K_v = \lim_{s \to 0} sG(s) = 0;$$

and
$$K_a = \lim_{s \to 0} s^2 G(s) = 0$$

b.

$$e_{step}(\infty) = \frac{1}{1 + \lim_{s \to 0} G(s)} = \frac{1}{1 + 127} = 7.8e - 03$$

$$e_{ramp}(\infty) = \frac{1}{\lim_{s \to 0} sG(s)} = \frac{1}{0} = \infty$$

$$e_{parabola}(\infty) = \frac{1}{\lim_{s \to 0} s^2G(s)} = \frac{1}{0} = \infty$$

System is stable for positive K. System is Type 0. Therefore, for a step input $e_{step}(\infty) = \frac{1}{1+K_p} = 0.1$. Solving for K_p yields $K_p = 9 = \lim_{s \to 0} G(s) = \frac{12K}{14^*18}$; from which we obtain K = 189.


7.4

System is stable. Since
$$G_1(s) = 1000$$
, and $G_2(s) = \frac{(s+2)}{(s+4)}$,

$$e_D(\infty) = -\frac{1}{\lim_{s \to 0} \frac{1}{G_2(s)} + \lim_{s \to 0} G_1(s)} = \frac{1}{2 + 1000} = -9.98e - 04$$

7.5

System is stable. Create a unity-feedback system, where $H_e(s) = \frac{1}{s+1} - 1 = \frac{-s}{s+1}$ The system is as follows:



Thus,

$$G_e(s) = \frac{G(s)}{1 + G(s)H_e(s)} = \frac{\frac{100}{(s+4)}}{1 - \frac{100s}{(s+1)(s+4)}} = \frac{100(s+1)}{s^2 - 95s + 4}$$

Hence, the system is Type 0. Evaluating K_p yields

$$K_p = \frac{100}{4} = 25$$

The steady-state error is given by

$$e_{step}(\infty) = \frac{1}{1 + K_p} = \frac{1}{1 + 25} = 3.846e - 02$$

7.6

Since
$$G(s) = \frac{K(s+7)}{s^2 + 2s + 10}$$
, $e(\infty) = \frac{1}{1 + K_p} = \frac{1}{1 + \frac{7K}{10}} = \frac{10}{10 + 7K}$.

Calculating the sensitivity, we get

$$S_{e:K} = \frac{K}{e} \frac{\partial e}{\partial K} = \frac{K}{\left(\frac{10}{10 + 7K}\right)} \frac{(-10)7}{\left(10 + 7K\right)^2} = -\frac{7K}{10 + 7K}$$

Given

$$\mathbf{A} = \begin{bmatrix} 0 & 1 \\ -3 & -6 \end{bmatrix}; \ \mathbf{B} = \begin{bmatrix} 0 \\ 1 \end{bmatrix}; \ \mathbf{C} = \begin{bmatrix} 1 & 1 \end{bmatrix}; \ \mathbf{R}(s) = \frac{1}{s}.$$

Using the final value theorem,

$$e_{step}(\infty) = \lim_{s \to 0} sR(s) \left[1 - \mathbf{C}(s\mathbf{I} - \mathbf{A})^{-1}\mathbf{B} \right] = \lim_{s \to 0} \left[1 - \begin{bmatrix} 1 & 1 \end{bmatrix} \begin{bmatrix} s & -1 \\ 3 & s + 6 \end{bmatrix}^{-1} \begin{bmatrix} 0 \\ 1 \end{bmatrix} \right]$$
$$= \lim_{s \to 0} \left[1 - \begin{bmatrix} 1 & 1 \end{bmatrix} \frac{\begin{bmatrix} s + 6 & 1 \\ -3s & s \end{bmatrix}}{s^2 + 6s + 3} \begin{bmatrix} 0 \\ 1 \end{bmatrix} \right] = \lim_{s \to 0} \frac{s^2 + 5s + 2}{s^2 + 6s + 3} = \frac{2}{3}$$


Using input substitution,

$$step(\infty) = 1 + \mathbf{C}\mathbf{A}^{-1}\mathbf{B} = 1 - \begin{bmatrix} 1 & 1 \end{bmatrix} \begin{bmatrix} 0 & 1 \\ -3 & -6 \end{bmatrix}^{-1} \begin{bmatrix} 0 \\ 1 \end{bmatrix}$$
$$= 1 + \begin{bmatrix} 1 & 1 \end{bmatrix} \frac{\begin{bmatrix} -6 & -1 \\ 3 & 0 \end{bmatrix}}{3} \begin{bmatrix} 0 \\ 1 \end{bmatrix} = 1 + \begin{bmatrix} 1 & 1 \end{bmatrix} \begin{bmatrix} -\frac{1}{3} \\ 0 \end{bmatrix} = \frac{2}{3}$$

CHAPTER 8

a.
$$F(-7+j9) = \frac{(-7+j9+2)(-7+j9+4)0.0339}{(-7+j9)(-7+j9+3)(-7+j9+6)} = \frac{(-5+j9)(-3+j9)}{(-7+j9)(-4+j9)(-1+j9)}$$
$$= \frac{(-66-j72)}{(944-j378)} = -0.0339 - j0.0899 = 0.096 < -110.7^{\circ}$$

b. The arrangement of vectors is shown as follows:




From the diagram,

$$F(-7+j9) = \frac{M_2M_4}{M_1M_3M_5} = \frac{(-3+j9)(-5+j9)}{(-1+j9)(-4+j9)(-7+j9)} = \frac{(-66-j72)}{(944-j378)}$$
$$= -0.0339 - j0.0899 = 0.096 <; -110.7^{\circ}$$

8.2

a. First draw the vectors.



From the diagram,

$$\sum \text{ angles} = 180^{\circ} - \tan^{-1} \left(\frac{-3}{-1} \right) - \tan^{-1} \left(\frac{-3}{1} \right) = 180^{\circ} - 108.43^{\circ} + 108.43^{\circ} = 180^{\circ}.$$

b. Since the angle is 180° , the point is on the root locus.

c.
$$K = \frac{\Pi \text{ pole lengths}}{\Pi \text{ zero lengths}} = \frac{\left(\sqrt{1^2 + 3^2}\right)\left(\sqrt{1^2 + 3^2}\right)}{1} = 10$$


8.3

First, find the asymptotes.

$$\sigma_a = \frac{\sum \text{poles} - \sum \text{zeros}}{\# \text{poles} - \# \text{zeros}} = \frac{(-2 - 4 - 6) - (0)}{3 - 0} = -4$$


$$\theta_a = \frac{(2k + 1)\pi}{3} = \frac{\pi}{3}, \ \pi, \ \frac{5\pi}{3}$$

Next draw root locus following the rules for sketching.



8.4

a.



b. Using the Routh-Hurwitz criteria, we first find the closed-loop transfer function.

$$T(s) = \frac{G(s)}{1 + G(s)} = \frac{K(s+2)}{s^2 + (K-4)s + (2K+13)}$$


Using the denominator of T(s), make a Routh table.

s^2	1	2K + 13
s^1	K - 40	0
s^0	2K + 13	0

We get a row of zeros for K = 4. From the s^2 row with K = 4, $s^2 + 21 = 0$. From which we evaluate the imaginary axis crossing at $\sqrt{21}$.

- **c.** From part (b), K = 4.
- **d.** Searching for the minimum gain to the left of -2 on the real axis yields -7 at a gain of 18. Thus the break-in point is at -7.


e. First, draw vectors to a point ε close to the complex pole.



At the point ε close to the complex pole, the angles must add up to zero. Hence, angle from zero – angle from pole in 4^{th} quadrant – angle from pole in 1^{st} quadrant = 180° , or $\tan^{-1}\left(\frac{3}{4}\right) - 90^{\circ} - \theta = 180^{\circ}$. Solving for the angle of departure, $\theta = -233.1$.


8.5

a.



- **b.** Search along the imaginary axis and find the 180° point at $s = \pm j4.06$.
- **c.** For the result in part (b), K = 1.
- **d.** Searching between 2 and 4 on the real axis for the minimum gain yields the break-in at s = 2.89.
- **e.** Searching along $\zeta = 0.5$ for the 180° point we find s = -2.42 + j4.18.
- **f.** For the result in part (e), K = 0.108.
- **g.** Using the result from part (c) and the root locus, K < 1.

a.



- **b.** Searching along the $\zeta = 0.591$ (10% overshoot) line for the 180° point yields -2.028 + j2.768 with K = 45.55.
- **c.** $T_s = \frac{4}{|\text{Re}|} = \frac{4}{2.028} = 1.97 \, s; \ T_p = \frac{\pi}{|\text{Im}|} = \frac{\pi}{2.768} = 1.13 \, s; \ \omega_n T_r = 1.8346 \ \text{from the}$ rise-time chart and graph in Chapter 4. Since ω_n is the radial distance to the pole, $\omega_n = \sqrt{2.028^2 + 2.768^2} = 3.431$. Thus, $T_r = 0.53 \, s$; since the system is Type 0, $K_p = \frac{K}{2^*4^*6} = \frac{45.55}{48} = 0.949$. Thus,

$$e_{step}(\infty) = \frac{1}{1 + K_p} = 0.51.$$


d. Searching the real axis to the left of -6 for the point whose gain is 45.55, we find -7.94. Comparing this value to the real part of the dominant pole, -2.028, we find that it is not five times further. The second-order approximation is not valid.

8.7

Find the closed-loop transfer function and put it the form that yields p_i as the root locus variable. Thus,


$$T(s) = \frac{G(s)}{1 + G(s)} = \frac{100}{s^2 + p_i s + 100} = \frac{100}{(s^2 + 100) + p_i s} = \frac{\frac{100}{s^2 + 100}}{1 + \frac{p_i s}{s^2 + 100}}$$

Hence, $KG(s)H(s) = \frac{p_i s}{s^2 + 100}$. The following shows the root locus.



8.8

Following the rules for plotting the root locus of positive-feedback systems, we obtain the following root locus:



8.9

The closed-loop transfer function is $T(s) = \frac{K(s+1)}{s^2 + (K+2)s + K}$. Differentiating the denominator with respect to K yields

$$2s\frac{\partial s}{\partial K} + (K+2)\frac{\partial s}{\partial K} + (s+1) = (2s+K+2)\frac{\partial s}{\partial K} + (s+1) = 0$$

Solving for
$$\frac{\partial s}{\partial K}$$
, we get $\frac{\partial s}{\partial K} = \frac{-(s+1)}{(2s+K+2)}$. Thus, $S_{s:K} = \frac{K}{s} \frac{\partial s}{\partial K} = \frac{-K(s+1)}{s(2s+K+2)}$.

Substituting
$$K = 20$$
 yields $S_{s:K} = \frac{-10(s+1)}{s(s+11)}$.

Now find the closed-loop poles when K = 20. From the denominator of T(s), $s_{1,2} = -21.05$, -0.95, when K = 20. For the pole at -21.05,

$$\Delta s = s(S_{s:K}) \frac{\Delta K}{K} = -12.05 \left(\frac{-10(-21.05+1)}{-21.05(-21.05+11)} \right) 0.05 = -0.9975.$$

For the pole at -0.95,

$$\Delta s = s(S_{s:K}) \frac{\Delta K}{K} = 0.95 \left(\frac{-10(-0.95+1)}{-0.95(-0.95+11)} \right) 0.05 = -0.0025.$$

CHAPTER 9

9.1

a. Searching along the 15% overshoot line, we find the point on the root locus at -3.5 + j5.8 at a gain of K = 45.84. Thus, for the uncompensated system, $K_{\nu} = \lim_{s \to 0} sG(s) = K/7 = 45.84/7 = 6.55$.

Hence, $e_{ramp_uncompensated}(\infty) = 1/K_v = 0.1527$.

- **b.** Compensator zero should be 20x further to the left than the compensator pole. Arbitrarily select $G_c(s) = \frac{(s+0.2)}{(s+0.01)}$.
- **c.** Insert compensator and search along the 15% overshoot line and find the root locus at -3.4 + j5.63 with a gain, K = 44.64. Thus, for the compensated system,

$$K_{\nu} = \frac{44.64(0.2)}{(7)(0.01)} = 127.5 \text{ and } e_{ramp_compensated}(\infty) = \frac{1}{K_{\nu}} = 0.0078.$$


d.
$$\frac{e_{ramp_uncompensated}}{e_{ramp_compensated}} = \frac{0.1527}{0.0078} = 19.58$$

9.2

a. Searching along the 15% overshoot line, we find the point on the root locus at -3.5 + j5.8 at a gain of K = 45.84. Thus, for the uncompensated system,

$$T_s = \frac{4}{|Re|} = \frac{4}{3.5} = 1.143 \, s.$$

b. The real part of the design point must be three times larger than the uncompensated pole's real part. Thus the design point is 3(-3.5)+j3(5.8)=-10.5+j17.4. The angular contribution of the plant's poles and compensator zero at the design point is 130.8° . Thus, the compensator pole must contribute $180^{\circ}-130.8^{\circ}=49.2^{\circ}$. Using the following diagram,




we find $\frac{17.4}{P_c - 10.5} = \tan 49.2^{\circ}$, from which, $p_c = 25.52$. Adding this pole, we find

the gain at the design point to be K=476.3. A higher-order closed-loop pole is found to be at -11.54. This pole may not be close enough to the closed-loop zero at -10. Thus, we should simulate the system to be sure the design requirements have been met.

a. Searching along the 20% overshoot line, we find the point on the root locus at -3.5 + 6.83 at a gain of K = 58.9. Thus, for the uncompensated system,

$$T_s = \frac{4}{|\text{Re}|} = \frac{4}{3.5} = 1.143 \, s.$$

- **b.** For the uncompensated system, $K_{\nu} = \lim_{s \to 0} sG(s) = K/7 = 58.9/7 = 8.41$. Hence, $e_{ramp_uncompensated}(\infty) = 1/K_{\nu} = 0.1189$.
- **c.** In order to decrease the settling time by a factor of 2, the design point is twice the uncompensated value, or $-7 + j \cdot 13.66$. Adding the angles from the plant's poles and the compensator's zero at -3 to the design point, we obtain -100.8° . Thus, the compensator pole must contribute $180^{\circ} 100.8^{\circ} = 79.2^{\circ}$. Using the following diagram,



we find $\frac{13.66}{P_c - 7} = \tan 79.2^{\circ}$, from which, $p_c = 9.61$. Adding this pole, we find the gain at the design point to be K = 204.9.

Evaluating K_{ν} for the lead-compensated system:

$$K_v = \lim_{s \to 0} sG(s)G_{lead} = K(3)/[(7)(9.61)] = (204.9)(3)/[(7)(9.61)] = 9.138.$$

 K_{ν} for the uncompensated system was 8.41. For a 10x improvement in steady-state error, K_{ν} must be (8.41)(10) = 84.1. Since lead compensation gave us $K_{\nu} = 9.138$, we need an improvement of 84.1/9.138 = 9.2. Thus, the lag compensator zero should be 9.2x further to the left than the compensator pole. Arbitrarily select


$$G_c(s) = \frac{(s+0.092)}{(s+0.01)}$$

Using all plant and compensator poles, we find the gain at the design point to be K = 205.4. Summarizing the forward path with plant, compensator, and gain yields

$$G_e(s) = \frac{205.4(s+3)(s+0.092)}{s(s+7)(9.61)(s+0.01)}.$$


Higher-order poles are found at -0.928 and -2.6. It would be advisable to simulate the system to see if there is indeed pole-zero cancellation.

The configuration for the system is shown in the figure below.



Minor-Loop Design:

For the minor loop, $G(s)H(s)=\frac{K_f}{(s+7)(s+10)}$. Using the following diagram, we find that the minor-loop root locus intersects the 0.7 damping ratio line at $-8.5+j\,8.67$. The imaginary part was found as follows: $\theta=\cos^{-1}\zeta=45.57^\circ$. Hence, $\frac{\mathrm{Im}}{8.5}=\tan 45.57^\circ$, from which $\mathrm{Im}=8.67$.



The gain, K_f , is found from the vector lengths as

$$K_f = \sqrt{1.5^2 + 8.67^2} \sqrt{1.5^2 + 8.67^2} = 77.42$$


Major-Loop Design:

Using the closed-loop poles of the minor loop, we have an equivalent forward-path transfer function of


$$G_e(s) = \frac{K}{s(s+8.5+j8.67)(s+8.5-j8.67)} = \frac{K}{s(s^2+17s+147.4)}.$$

Using the three poles of $G_e(s)$ as open-loop poles to plot a root locus, we search along $\zeta = 0.5$ and find that the root locus intersects this damping ratio line at -4.34 + j7.51 at a gain, K = 626.3.

a. An active PID controller must be used. We use the circuit shown in the following figure:



where the impedances are shown below as follows:



Matching the given transfer function with the transfer function of the PID controller yields

$$G_c(s) = \frac{(s+0.1)(s+5)}{s} = \frac{s^2 + 5.1s + 0.5}{s} = s + 5.1 + \frac{0.5}{8}$$
$$= -\left[\left(\frac{R_2}{R_1} + \frac{C_1}{C_2} \right) + R_2 C_1 s + \frac{1}{\frac{R_1 C_2}{s}} \right]$$

Equating coefficients


$$\frac{1}{R_1 C_2} = 0.5 \tag{1}$$

$$R_2C_1 = 1 \tag{2}$$

$$\left(\frac{R_2}{R_1} + \frac{C_1}{C_2}\right) = 5.1$$
(3)

In Eq. (2) we arbitrarily let $C_1 = 10^{-5}$. Thus, $R_2 = 10^5$. Using these values along with Eqs. (1) and (3) we find $C_2 = 100\mu F$ and $R_1 = 20 \text{ k}\Omega$.

b. The lag-lead compensator can be implemented with the following passive network, since the ratio of the lead pole-to-zero is the inverse of the ratio of the lag pole-to-zero:



Matching the given transfer function with the transfer function of the passive lag-lead compensator yields

$$G_c(s) = \frac{(s+0.1)(s+2)}{(s+0.01)(s+20)} = \frac{(s+0.1)(s+2)}{s^2+20.01s+0.2}$$
$$= \frac{\left(s+\frac{1}{R_1C_1}\right)\left(s+\frac{1}{R_2C_2}\right)}{s^2+\left(\frac{1}{R_1C_1}+\frac{1}{R_2C_2}+\frac{1}{R_2C_1}\right)s+\frac{1}{R_1R_2C_1C_2}}$$

Equating coefficients

$$\frac{1}{R_1 C_1} = 0.1 \tag{1}$$

$$\frac{1}{R_2 C_2} = 0.1 \tag{2}$$

$$\left(\frac{1}{R_1C_1} + \frac{1}{R_2C_2} + \frac{1}{R_2C_1}\right) = 20.01\tag{3}$$

Substituting Eqs. (1) and (2) in Eq. (3) yields

$$\frac{1}{R_2C_1} = 17.91\tag{4}$$

Arbitrarily letting $C_1 = 100 \,\mu F$ in Eq. (1) yields $R_1 = 100 \,k\Omega$. Substituting $C_1 = 100 \,\mu F$ into Eq. (4) yields $R_2 = 558 \,k\Omega$. Substituting $R_2 = 558 \,k\Omega$ into Eq. (2) yields $C_2 = 900 \,\mu F$.

CHAPTER 10


10.1

a.


$$G(s) = \frac{1}{(s+2)(s+4)}; \ G(j\omega) = \frac{1}{(8+\omega^2) + j6\omega}$$
$$M(\omega) = \sqrt{(8-\omega^2)^2 + (6\omega)^2}$$

For
$$\omega < \sqrt{8}$$
, $\phi(\omega) = -\tan^{-1}\left(\frac{6\omega}{8 - \omega^2}\right)$.
For $\omega < \sqrt{8}$, $\phi(\omega) = -\left(\pi + \tan^{-1}\left[\frac{6\omega}{8 - \omega^2}\right]\right)$.


b.




c.



10.2




The frequency response is 1/8 at an angle of zero degrees at $\omega=0$. Each pole rotates 90° in going from $\omega=0$ to $\omega=\infty$. Thus, the resultant rotates -180° while its magnitude goes to zero. The result is shown below.



10.4

a. The frequency response is 1/48 at an angle of zero degrees at $\omega=0$. Each pole rotates 90° in going from $\omega=0$ to $\omega=\infty$. Thus, the resultant rotates -270° while its magnitude goes to zero. The result is shown below.




b. Substituting $j\omega$ into $G(s)=\frac{1}{(s+2)(s+4)(s+6)}=\frac{1}{s^3+12s^2+44s+48}$ and simplifying, we obtain $G(j\omega)=\frac{(48-12\omega^2)-j(44\omega-\omega^3)}{\omega^6+56\omega^4+784\omega^2+2304}$. The Nyquist diagram crosses the real axis when the imaginary part of $G(j\omega)$ is zero. Thus, the Nyquist diagram crosses the real axis at $\omega^2=44$, or $\omega=\sqrt{44}=6.63$ rad/s. At this frequency $G(j\omega)=-\frac{1}{480}$. Thus, the system is stable for K<480.

If K = 100, the Nyquist diagram will intersect the real axis at -100/480. Thus, $G_M = 20 \log \frac{480}{100} = 13.62$ dB. From Skill-Assessment Exercise Solution 10.4, the 180° frequency is 6.63 rad/s.

10.6

a.



0 -50 -50 -100 -200 -250 -300 1 10 100 1000

b. The phase angle is 180° at a frequency of 36.74 rad/s. At this frequency the gain is -99.67 dB. Therefore, $20 \log K = 99.67$, or K = 96,270. We conclude that the system is stable for K < 96,270.

Frequency (rad/s)


c. For K=10,000, the magnitude plot is moved up $20\log 10,000=80$ dB. Therefore, the gain margin is 99.67-80=19.67 dB. The 180° frequency is 36.7 rad/s. The gain curve crosses 0 dB at $\omega=7.74$ rad/s, where the phase is 87.1° . We calculate the phase margin to be $180^\circ-87.1^\circ=92.9^\circ$.

10.7


Using $\zeta = \frac{-\ln(\%/100)}{\sqrt{\pi^2 + \ln^2(\%100)}}$, we find $\zeta = 0.456$, which corresponds to 20% overshoot. Using $T_s = 2$, $\omega_{BW} = \frac{4}{T_s \zeta} \sqrt{(1 - 2\zeta^2) + \sqrt{4\zeta^4 - 4}\zeta^2 + 2} = 5.79 \, \text{rad/s}$.

For both parts find that $G(j\omega)=\frac{160}{27}*\frac{\left(6750000-101250\omega^2\right)+j1350\left(\omega^2-1350\right)\omega}{\omega^6+2925\omega^4+1072500\omega^2+25000000}.$ For a range of values for ω , superimpose $G(j\omega)$ on the **a.** M and N circles, and on the **b.** Nichols chart.


a.




b.



Plotting the closed-loop frequency response from a. or b. yields the following plot:



10.9 The open-loop frequency response is shown in the following figure:



The open-loop frequency response is -7 at $\omega = 14.5 \, \mathrm{rad/s}$. Thus, the estimated bandwidth is $\omega_{WB} = 14.5 \, \mathrm{rad/s}$. The open-loop frequency response plot goes through zero dB at a frequency of 9.4 rad/s, where the phase is 151.98° . Hence, the phase margin is $180^{\circ} - 151.98^{\circ} = 28.02^{\circ}$. This phase margin corresponds to

$$\zeta = 0.25$$
. Therefore, $\%OS = e^{-\left(\zeta\pi/\sqrt{1-\zeta^2}\right)} \times 100 = 44.4\%$

$$T_s = \frac{4}{\omega_{BW}\zeta}\sqrt{(1-2\zeta^2) + \sqrt{4\zeta^4 - 4\zeta^2 + 2}} = 1.64 \text{ s and}$$

$$T_p = \frac{\pi}{\omega_{BW}\sqrt{1-\zeta^2}}\sqrt{(1-2\zeta^2) + \sqrt{4\zeta^4 - 4\zeta^2 + 2}} = 0.33 \text{ s}$$

10.10

The initial slope is 40 dB/dec. Therefore, the system is Type 2. The initial slope intersects 0 dB at $\omega = 9.5 \,\text{rad/s}$. Thus, $K_a = 9.5^2 = 90.25$ and $K_p = K_v = \infty$.

10.11

- **a.** Without delay, $G(j\omega) = \frac{10}{j\omega(j\omega+1)} = \frac{10}{\omega(-\omega+j)}$, from which the zero dB frequency is found as follows: $M = \frac{10}{\omega\sqrt{\omega^2+1}} = 1$. Solving for ω , $\omega\sqrt{\omega^2+1} = 10$, or after squaring both sides and rearranging, $\omega^4 + \omega^2 100 = 0$. Solving for the roots, $\omega^2 = -10.51$, 9.51. Taking the square root of the positive root, we find the 0 dB frequency to be 3.08 rad/s. At this frequency, the phase angle, $\phi = -2(-\omega+j) = -2(-3.08+j) = -162^\circ$. Therefore the phase margin is $180^\circ -162^\circ = 18^\circ$.
- **b.** With a delay of 0.1 s,

$$\phi = -\angle(-\omega + j) - \omega T = -\angle(-3.08 + j) - (3.08)(0.1)(180/\text{pi})$$

= -162 - 17.65 = -179.65°

Therefore the phase margin is $180^{\circ} - 179.65^{\circ} = 0.35^{\circ}$. Thus, the system is table. **c.** With a delay of 3 s,


$$\phi = -\angle(-\omega + j) - \omega T = -\angle(-3.08 + j) - (3.08)(3)(180/\text{pi}) = -162^{\circ} - 529.41^{\circ}$$

= -691.41° = 28.59 deg.


Therefore the phase margin is 28.59 - 180 = -151.41 deg. Thus, the system is unstable.

10.12

Drawing judicially selected slopes on the magnitude and phase plot as shown below yields a first estimate.



We see an initial slope on the magnitude plot of -20 dB/dec. We also see a final -20 dB/dec slope with a break frequency around 21 rad/s. Thus, an initial estimate is $G_1(s) = \frac{1}{s(s+21)}$. Subtracting $G_1(s)$ from the original frequency response yields the frequency response shown below.




Drawing judicially selected slopes on the magnitude and phase plot as shown yields a final estimate. We see first-order zero behavior on the magnitude and phase plots with a break frequency of about 5.7 rad/s and a dc gain of about $44 \, \mathrm{dB} = 20 \log(5.7K)$, or K = 27.8. Thus, we estimate $G_2(s) = 27.8(s+7)$. Thus, $G(s) = G_1(s)G_2(s) = \frac{27.8(s+5.7)}{s(s+21)}$. It is interesting to note that the original problem was developed from $G(s) = \frac{30(s+5)}{s(s+20)}$.

CHAPTER 11

11.1

The Bode plot for K = 1 is shown below.




A 20% overshoot requires
$$\zeta = \frac{-\log\left(\frac{\%}{100}\right)}{\sqrt{\pi^2 + \log^2\left(\frac{\%}{100}\right)}} = 0.456$$
. This damping ratio implies a

phase margin of 48.10, which is obtained when the phase angle = -1800 + 48.10 $= 131.9^{\circ}$. This phase angle occurs at $\omega = 27.6 \, \text{rad/s}$. The magnitude at this frequency is 5.15×10^{-6} . Since the magnitude must be unity $K = \frac{1}{5.15 \times 10^{-6}} = 194,200$.

11.2

To meet the steady-state error requirement, K = 1,942,000. The Bode plot for this gain is shown below.




A 20% overshoot requires
$$\zeta = \frac{-\log\left(\frac{\%}{100}\right)}{\sqrt{\pi^2 + \log^2\left(\frac{\%}{100}\right)}} = 0.456$$
. This damping ratio

implies a phase margin of 48.1°. Adding 10° to compensate for the phase angle contribution of the lag, we use 58.1° . Thus, we look for a phase angle of $-180^\circ + 58.1^\circ = -129.9^\circ$. The frequency at which this phase occurs is 20.4 rad/s. At this frequency the magnitude plot must go through zero dB. Presently, the magnitude plot is 23.2 dB. Therefore draw the high frequency asymptote of the lag compensator at -23.2 dB. Insert a break at 0.1(20.4) = 2.04 rad/s. At this frequency, draw -23.2 dB/dec slope until it intersects 0 dB. The frequency of intersection will be the low frequency break or 0.141 rad/s. Hence the compensator is $G_c(s) = K_c \frac{(s+2.04)}{(s+0.141)}$, where the gain is chosen to yield 0 dB at low frequencies, or $K_c = 0.141/2.04 = 0.0691$. In summary,

$$G_c(s) = 0.0691 \frac{(s+2.04)}{(s+0.141)} \text{ and } G(s) = \frac{1,942,000}{s(s+50)(s+120)}$$

11.3

A 20% overshoot requires $\zeta = \frac{-\log\left(\frac{\%}{100}\right)}{\sqrt{\pi^2 + \log^2\left(\frac{\%}{100}\right)}} = 0.456$. The required bandwidth is then calculated as $\omega_{BW} = \frac{4}{T_s\zeta}\sqrt{(1-2\zeta^2)+\sqrt{4\zeta^4-4\zeta^2+2}} = 57.9$ rad/s. In order to meet the steady-state error requirement of $K_\nu = 50 = \frac{K}{(50)(120)}$, we calculate K = 300,000. The uncompensated Bode plot for this gain is shown below.



The uncompensated system's phase margin measurement is taken where the magnitude plot crosses 0 dB. We find that when the magnitude plot crosses 0 dB, the phase angle is -144.8° . Therefore, the uncompensated system's phase margin is $-180^{\circ} + 144.8^{\circ} = 35.2^{\circ}$. The required phase margin based on the required damping ratio is $\Phi_M = \tan^{-1} \frac{2\zeta}{\sqrt{-2\zeta^2 + \sqrt{1+4\zeta^4}}} = 48.1^{\circ}$. Adding a 10° correction factor, the

required phase margin is 58.1° . Hence, the compensator must contribute $\phi_{\max} = 58.1^{\circ} - 35.2^{\circ} = 22.9^{\circ}$. Using $\phi_{\max} = \sin^{-1}\frac{1-\beta}{1+\beta}$, $\beta = \frac{1-\sin\phi_{\max}}{1+\sin\phi_{\max}} = 0.44$.

The compensator's peak magnitude is calculated as $M_{\text{max}} = \frac{1}{\sqrt{\beta}} = 1.51$. Now find the frequency at which the uncompensated system has a magnitude $1/M_{\text{max}}$, or -3.58 dB. From the Bode plot, this magnitude occurs at $\omega_{\text{max}} = 50 \, \text{rad/s}$. The compensator's zero is at $z_c = \frac{1}{T}$. $\omega_{\text{max}} = \frac{1}{T\sqrt{\beta}}$ Therefore, $z_c = 33.2$.

The compensator's pole is at $P_c = \frac{1}{\beta T} = \frac{z_c}{\beta} = 75.4$. The compensator gain is chosen to yield unity gain at dc.


Hence,
$$K_c = 75.4/33.2 = 2.27$$
. Summarizing, $G_c(s) = 2.27 \frac{(s+33.2)}{(s+75.4)}$, and $G(s) \frac{300,000}{s(s+50)(s+120)}$.

11.4

A 10% overshoot requires
$$\zeta = \frac{-\log\left(\frac{\%}{100}\right)}{\sqrt{\pi^2 + \log^2\left(\frac{\%}{100}\right)}} = 0.591$$
. The required bandwidth

is then calculated as
$$\omega_{BW} = \frac{\pi}{T_p \sqrt{1 - \zeta^2}} \sqrt{(1 - 2\zeta^2) + \sqrt{4\zeta^4 - 4\zeta^2 + 2}} = 7.53 \text{ rad/s}.$$

In order to meet the steady-state error requirement of $K_{\nu} = 10 = \frac{K}{(8)(30)}$, we calculate K = 2400. The uncompensated Bode plot for this gain is shown below.



Let us select a new phase-margin frequency at $0.8\omega_{BW}=6.02\,\mathrm{rad/s}$. The required phase margin based on the required damping ratio is $\Phi_M=\tan^{-1}$

$$\frac{2\zeta}{\sqrt{-2\zeta^2+\sqrt{1+4\zeta^4}}}=58.6^\circ$$
. Adding a 5° correction factor, the required phase

margin is 63.6° . At 6.02 rad/s, the new phase-margin frequency, the phase angle is–which represents a phase margin of $180^{\circ} - 138.3^{\circ} = 41.7^{\circ}$. Thus, the lead compensator must contribute $\phi_{\rm max} = 63.6^{\circ} - 41.7^{\circ} = 21.9^{\circ}$.

Using
$$\phi_{\text{max}} = \sin^{-1}\frac{1-\beta}{1+\beta}$$
, $\beta = \frac{1-\sin\phi_{\text{max}}}{1+\sin\phi_{\text{max}}} = 0.456$.

We now design the lag compensator by first choosing its higher break frequency one decade below the new phase-margin frequency, that is, $z_{lag} = 0.602 \, \text{rad/s}$. The lag compensator's pole is $p_{lag} = \beta z_{lag} = 0.275$. Finally, the lag compensator's gain is $K_{lag} = \beta = 0.456$.

Now we design the lead compensator. The lead zero is the product of the new phase margin frequency and $\sqrt{\beta}$, or $z_{lead} = 0.8\omega_{BW}\sqrt{\beta} = 4.07$. Also, $p_{lead} = \frac{z_{lead}}{\beta}$

= 8.93. Finally,
$$K_{lead} = \frac{1}{\beta} = 2.19$$
. Summarizing,

$$G_{lag} = (s) = 0.456 \frac{(s+0.602)}{(s+0.275)}; G_{lead}(s) = 2.19 \frac{(s+4.07)}{(s+8.93)}; \text{ and } k = 2400.$$

CHAPTER 12

12.1

We first find the desired characteristic equation. A 5% overshoot requires

$$\zeta = \frac{-\log\left(\frac{\%}{100}\right)}{\sqrt{\pi^2 + \log^2\left(\frac{\%}{100}\right)}} = 0.69. \text{ Also, } \omega_n = \frac{\pi}{T_p\sqrt{1-\zeta^2}} = 14.47 \text{ rad/s. Thus, the characteristic equation is } s^2 + 2\zeta\omega_n s + \omega_n^2 = s^2 + 19.97s + 209.4. \text{ Adding a pole at } -10 \text{ to cancel the zero at } -10 \text{ yields the desired characteristic equation,}$$

 $(s^2 + 19.97s + 209.4)(s + 10) = s^3 + 29.97s^2 + 409.1s + 2094$. The compensated system matrix in phase-variable form is

$$\mathbf{A} - \mathbf{B}\mathbf{K} = \begin{bmatrix} 0 & 1 & 0 \\ 0 & 0 & 1 \\ -(k_1) & -(36+k_2) & -(15+k_3) \end{bmatrix}.$$
 The characteristic equation for this

system is $|s\mathbf{I} - (\mathbf{A} - \mathbf{B}\mathbf{K})| = s^3 + (15 + k_3)s^2 + (36 + k_2)s + (k_1)$. Equating coefficients of this equation with the coefficients of the desired characteristic equation yields the gains as

$$\mathbf{K} = [k_1 \quad k_2 \quad k_3] = [2094 \quad 373.1 \quad 14.97].$$

12.2

The controllability matrix is $\mathbf{C}_{\mathbf{M}} = \begin{bmatrix} \mathbf{B} & \mathbf{A}\mathbf{B} & \mathbf{A}^2\mathbf{B} \end{bmatrix} = \begin{bmatrix} 2 & 1 & 1 \\ 1 & 4 & -9 \\ 1 & -1 & 16 \end{bmatrix}$. Since

 $|\mathbf{C}_{\mathbf{M}}| = 80$, $\mathbf{C}_{\mathbf{M}}$ is full rank, that is, rank 3. We conclude that the system is controllable.

12.3

First check controllability. The controllability matrix is $C_{Mz} = \begin{bmatrix} \mathbf{B} & \mathbf{A}\mathbf{B} & \mathbf{A}^2\mathbf{B} \end{bmatrix} =$

$$\begin{bmatrix} 0 & 0 & 1 \\ 0 & 1 & -17 \\ 1 & -9 & 81 \end{bmatrix}$$
. Since $|\mathbf{C_{Mz}}| = -1$, $\mathbf{C_{Mz}}$ is full rank, that is, rank 3. We conclude that

the system is controllable. We now find the desired characteristic equation. A 20%

overshoot requires
$$\zeta = \frac{-\log\left(\frac{\%}{100}\right)}{\sqrt{\pi^2 + \log^2\left(\frac{\%}{100}\right)}} = 0.456$$
. Also, $\omega_n = \frac{4}{\zeta T_s} = 4.386 \,\text{rad/s}$.

Thus, the characteristic equation is $s^2 + 2\zeta\omega_n s + \omega_n^2 = s^2 + 4s + 19.24$. Adding a pole at -6 to cancel the zero at -6 yields the resulting desired characteristic equation,

$$(s^2 + 4s + 19.24)(s + 6) = s^3 + 10s^2 + 43.24s + 115.45.$$

Since $G(s) = \frac{(s+6)}{(s+7)(s+8)(s+9)} = \frac{s+6}{s^3+24s^2+191s+504}$, we can write the phase-

variable representation as $\mathbf{A_p} = \begin{bmatrix} 0 & 1 & 0 \\ 0 & 0 & 1 \\ -504 & -191 & -24 \end{bmatrix}$; $\mathbf{B_p} = \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix}$; $\mathbf{C_p} = \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix}$

[6 1 0]. The compensated system matrix in phase-variable form is $\mathbf{A_p} - \mathbf{B_p K_p} = \begin{bmatrix} 0 & 1 & 0 \\ 0 & 0 & 1 \\ -(504+k_1) & -(191+k_2) & -(24+k_3) \end{bmatrix}$. The characteristic equation for this

system is $|s\mathbf{I} - (\mathbf{A_p} - \mathbf{B_pK_p})| = s^3 + (24 + k_3)s^2 + (191 + k_2)s + (504 + k_1)$. Equating coefficients of this equation with the coefficients of the desired characteristic equation yields the gains as $\mathbf{K_p} = \begin{bmatrix} k_1 & k_2 & k_3 \end{bmatrix} = \begin{bmatrix} -388.55 & -147.76 & -14 \end{bmatrix}$. We now develop the transformation matrix to transform back to the *z*-system.

$$\mathbf{C}_{\mathbf{M}z} = \begin{bmatrix} \mathbf{B}_z & \mathbf{A}_z \mathbf{B}_z & \mathbf{A}_z^2 \mathbf{B}_z \end{bmatrix} = \begin{bmatrix} 0 & 0 & 1 \\ 0 & 1 & -17 \\ 1 & -9 & 81 \end{bmatrix} \text{ and }$$

$$\mathbf{C}_{\mathbf{Mp}} = \begin{bmatrix} \mathbf{B_p} & \mathbf{A_p B_p} & \mathbf{A_p^2 B_p} \end{bmatrix} = \begin{bmatrix} 0 & 0 & 1 \\ 0 & 1 & -24 \\ 1 & -24 & 385 \end{bmatrix}.$$

Therefore,

$$\mathbf{P} = \mathbf{C}_{\mathbf{M}z} \mathbf{C}_{\mathbf{M}x}^{-1} = \begin{bmatrix} 0 & 0 & 1 \\ 0 & 1 & -17 \\ 1 & -9 & 81 \end{bmatrix} \begin{bmatrix} 191 & 24 & 1 \\ 24 & 1 & 0 \\ 1 & 0 & 0 \end{bmatrix} = \begin{bmatrix} 1 & 0 & 0 \\ 7 & 1 & 0 \\ 56 & 15 & 1 \end{bmatrix}$$

Hence,
$$\mathbf{K}_z = \mathbf{K}_{\mathbf{p}} \mathbf{P}^{-1} = \begin{bmatrix} -388.55 & -147.76 & -14 \end{bmatrix} \begin{bmatrix} 1 & 0 & 0 \\ -7 & 1 & 0 \\ 49 & -15 & 1 \end{bmatrix}$$

= $\begin{bmatrix} -40.23 & 62.24 & -14 \end{bmatrix}$.

12.4

For the given system
$$\mathbf{e}_{\dot{\mathbf{x}}} = (\mathbf{A} - \mathbf{LC})\mathbf{e}_{\mathbf{x}} = \begin{bmatrix} -(24+l_1) & 1 & 0 \\ -(191+l_2) & 0 & 1 \\ -(504+l_3) & 0 & 0 \end{bmatrix} \mathbf{e}_{\mathbf{x}}$$
. The characteristic

polynomial is given by $|[s\mathbf{I} - (\mathbf{A} - \mathbf{LC})]| = s^3 + (24 + l_1)s^2 + (191 + l_2)s + (504 + l_3)$. Now we find the desired characteristic equation. The dominant poles from Skill-Assessment Exercise 12.3 come from $(s^2 + 4s + 19.24)$. Factoring yields (-2 + j3.9) and (-2 - j3.9). Increasing these poles by a factor of 10 and adding a third pole 10 times the real part of the dominant second-order poles yields the

desired characteristic polynomial, $(s + 20 + j39)(s + 20 - j39)(s + 200) = s^3 + 240s^2 + 9921s + 384200$. Equating coefficients of the desired characteristic equation to the

system's characteristic equation yields
$$\mathbf{L} = \begin{bmatrix} 216 \\ 9730 \\ 383696 \end{bmatrix}$$
.

12.5

The observability matrix is
$$\mathbf{O_M} = \begin{bmatrix} \mathbf{C} \\ \mathbf{CA} \\ \mathbf{CA}^2 \end{bmatrix} = \begin{bmatrix} 4 & 6 & 8 \\ -64 & -80 & -78 \\ 674 & 848 & 814 \end{bmatrix}$$
, where

$$\mathbf{A}^{2} = \begin{bmatrix} 25 & 28 & 32 \\ -7 & -4 & -11 \\ 77 & 95 & 94 \end{bmatrix}.$$
 The matrix is of full rank, that is, rank 3, since

 $|\mathbf{O}_{\mathbf{M}}| = -1576$. Therefore the system is observable.

12.6

The system is represented in cascade form by the following state and output equations:

$$\dot{\mathbf{z}} = \begin{bmatrix} -7 & 1 & 0 \\ 0 & -8 & 1 \\ 0 & 0 & -9 \end{bmatrix} \mathbf{z} + \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix} u$$

$$y = [1 \quad 0 \quad 0]\mathbf{z}$$

The observability matrix is $\mathbf{O_{Mz}} = \begin{bmatrix} \mathbf{C_z} \\ \mathbf{C_z A_z} \\ \mathbf{C_z A_z}^2 \end{bmatrix} = \begin{bmatrix} 1 & 0 & 0 \\ -7 & 1 & 0 \\ 49 & -15 & 1 \end{bmatrix}$,

where
$$\mathbf{A}_{\mathbf{z}}^2 = \begin{bmatrix} 49 & -15 & 1 \\ 0 & 64 & -17 \\ 0 & 0 & 81 \end{bmatrix}$$
. Since $G(s) = \frac{1}{(s+7)(s+8)(s+9)}$

 $=\frac{1}{s^3+24s^2+191s+504}$, we can write the observable canonical form as

$$\dot{\mathbf{x}} = \begin{bmatrix} -24 & 1 & 0 \\ -191 & 0 & 1 \\ -504 & 0 & 0 \end{bmatrix} \mathbf{x} + \begin{bmatrix} 0 \\ 0 \\ 1 \end{bmatrix} u$$

$$y = [1 \quad 0 \quad 0]\mathbf{x}$$

The observability matrix for this form is $\mathbf{O_{Mx}} = \begin{bmatrix} \mathbf{C_x} \\ \mathbf{C_x A_x} \\ \mathbf{C_x A_x}^2 \end{bmatrix} = \begin{bmatrix} 1 & 0 & 0 \\ -24 & 1 & 0 \\ 385 & -24 & 1 \end{bmatrix}$,

where

$$\mathbf{A}_{\mathbf{x}}^2 = \begin{bmatrix} 385 & -24 & 1\\ 4080 & -191 & 0\\ 12096 & 504 & 0 \end{bmatrix}.$$

We next find the desired characteristic equation. A 10% overshoot requires

$$\zeta = \frac{-\log\left(\frac{\%}{100}\right)}{\sqrt{\pi^2 + \log^2\left(\frac{\%}{100}\right)}} = 0.591. \text{ Also, } \omega_n = \frac{4}{\zeta T_s} = 67.66 \text{ rad/s. Thus, the characteristic}$$

equation is $s^2 + 2\zeta\omega_n s + \omega_n^2 = s^2 + 80s + 4578.42$. Adding a pole at -400, or 10 times the real part of the dominant second-order poles, yields the resulting desired characteristic equation, $(s^2 + 80s + 4578.42)(s + 400) = s^3 + 480s^2 + 36580s + 1.831x10^6$. For the system represented in observable canonical form $\mathbf{e_x} = (\mathbf{A_x} - \mathbf{L_x}\mathbf{C_x}) \mathbf{e_x} = (\mathbf{A_x} - \mathbf{L_x}\mathbf{C_x}) \mathbf$

$$\begin{bmatrix} -(24+l_1) & 1 & 0 \\ -(191+l_2) & 0 & 1 \\ -(504+l_3) & 0 & 0 \end{bmatrix} \mathbf{e_x}.$$
 The characteristic polynomial is given by

 $|[s\mathbf{I} - (\mathbf{A_x} - \mathbf{L_x}\mathbf{C_x})]| = s^3 + (24 + l_1)s^2 + (191 + l_2)s + (504 + l_3)$. Equating coefficients of the desired characteristic equation to the system's characteristic equation

yields
$$\mathbf{L_x} = \begin{bmatrix} 456 \\ 36,389 \\ 1,830,496 \end{bmatrix}$$
.

Now, develop the transformation matrix between the observer canonical and cascade forms.

$$\mathbf{P} = \mathbf{O}_{\mathbf{Mz}}^{-1} \mathbf{O}_{\mathbf{Mx}} = \begin{bmatrix} 1 & 0 & 0 \\ -7 & 1 & 0 \\ 49 & -15 & 1 \end{bmatrix}^{-1} \begin{bmatrix} 1 & 0 & 0 \\ -24 & 1 & 0 \\ 385 & -24 & 1 \end{bmatrix}$$
$$= \begin{bmatrix} 1 & 0 & 0 \\ 7 & 1 & 0 \\ 56 & 15 & 1 \end{bmatrix} \begin{bmatrix} 1 & 0 & 0 \\ -24 & 1 & 0 \\ 385 & -24 & 1 \end{bmatrix}$$
$$= \begin{bmatrix} 1 & 0 & 0 \\ -17 & 1 & 0 \\ 81 & -9 & 1 \end{bmatrix}$$

Finally,

$$\mathbf{L_z} = \mathbf{PL_x} = \begin{bmatrix} 1 & 0 & 0 \\ -17 & 1 & 0 \\ 81 & -9 & 1 \end{bmatrix} \begin{bmatrix} 456 \\ 36,389 \\ 1,830,496 \end{bmatrix} = \begin{bmatrix} 456 \\ 28,637 \\ 1,539,931 \end{bmatrix} \approx \begin{bmatrix} 456 \\ 28,640 \\ 1,540,000 \end{bmatrix}.$$

We first find the desired characteristic equation. A 10% overshoot requires

$$\zeta = \frac{-\log\left(\frac{\%}{100}\right)}{\sqrt{\pi^2 + \log^2\left(\frac{\%}{100}\right)}} = 0.591$$

Also, $\omega_n = \frac{\pi}{T_p \sqrt{1-\zeta^2}} = 1.948 \,\text{rad/s}$. Thus, the characteristic equation is $s^2 +$

 $2\zeta\omega_n s + \omega_n^2 = s^2 + 2.3s + 3.79$. Adding a pole at -4, which corresponds to the original system's zero location, yields the resulting desired characteristic equation, $(s^2 + 2.3s + 3.79)(s + 4) = s^3 + 6.3s^2 + 13s + 15.16$.

Now,
$$\begin{bmatrix} \dot{\mathbf{x}} \\ \dot{x}_N \end{bmatrix} = \begin{bmatrix} (\mathbf{A} - \mathbf{B}\mathbf{K}) & \mathbf{B}K_e \\ -\mathbf{C} & 0 \end{bmatrix} \begin{bmatrix} \mathbf{x} \\ x_N \end{bmatrix} + \begin{bmatrix} \mathbf{0} \\ 1 \end{bmatrix} r$$
; and $y = \begin{bmatrix} \mathbf{C} & 0 \end{bmatrix} \begin{bmatrix} \mathbf{x} \\ x_N \end{bmatrix}$,

where

$$\mathbf{A} - \mathbf{B}\mathbf{K} = \begin{bmatrix} 0 & 1 \\ -7 & -9 \end{bmatrix} - \begin{bmatrix} 0 \\ 1 \end{bmatrix} [k_1 \quad k_2] = \begin{bmatrix} 0 & 1 \\ -7 & -9 \end{bmatrix} - \begin{bmatrix} 0 & 0 \\ k_1 & k_2 \end{bmatrix}$$
$$= \begin{bmatrix} 0 & 1 \\ -(7+k_1) & -(9+k_2) \end{bmatrix}$$
$$\mathbf{C} = \begin{bmatrix} 4 & 1 \end{bmatrix}$$
$$\mathbf{B}k_e = \begin{bmatrix} 0 \\ 1 \end{bmatrix} k_e = \begin{bmatrix} 0 \\ k_e \end{bmatrix}$$

Thus,

$$\begin{bmatrix} \dot{x_1} \\ \dot{x_2} \\ \dot{x_N} \end{bmatrix} = \begin{bmatrix} 0 & 1 & 0 \\ -(7+k_1) & -(9+k_2) & k_e \\ -4 & -1 & 0 \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \\ x_N \end{bmatrix} + \begin{bmatrix} \mathbf{0} \\ 1 \end{bmatrix} r; \ y = \begin{bmatrix} 4 & 1 & 0 \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \\ x_N \end{bmatrix}.$$

Finding the characteristic equation of this system yields

$$\begin{vmatrix} s\mathbf{I} - \begin{bmatrix} (\mathbf{A} - \mathbf{B}\mathbf{K}) & \mathbf{B}K_e \\ -\mathbf{C} & 0 \end{bmatrix} \end{vmatrix} = \begin{vmatrix} \begin{bmatrix} s & 0 & 0 \\ 0 & s & 0 \\ 0 & 0 & s \end{bmatrix} - \begin{bmatrix} 0 & 1 & 0 \\ -(7 + k_1) & -(9 + k_2) & k_e \\ -4 & -1 & 0 \end{bmatrix} \end{vmatrix}$$
$$= \begin{vmatrix} \begin{bmatrix} s & -1 & 0 \\ (7 + k_1) & s + (9 + k_2) & -k_e \\ 4 & 1 & s \end{vmatrix} \end{vmatrix} = s^3 + (9 + k_2)s^2 + (7 + k_1 + k_e)s + 4k_e$$

Equating this polynomial to the desired characteristic equation.

$$s^{3} + 6.3s^{2} + 13s + 15.16 = s^{3} + (9 + k_{2})s^{2} + (7 + k_{1} + k_{e})s + 4k_{e}$$

Solving for the k's,

$$\mathbf{K} = [2.21 \quad -2.7] \text{ and } k_e = 3.79.$$

CHAPTER 13

13.1

$$f(t) = \sin(\omega kT); f^*(t) = \sum_{k=0}^{\infty} \sin(\omega kT)\delta(t - kT);$$

$$F^*(s) = \sum_{k=0}^{\infty} \sin(\omega kT)e^{-kTs} = \sum_{k=0}^{\infty} \frac{(e^{j\omega kT} - e^{-j\omega kT})e^{-kTs}}{2j}$$

$$= \frac{1}{2j} \sum_{k=0}^{\infty} (e^{T(s-j\omega)})^{-k} - (e^{T(s+j\omega)})^{-k}$$

But,
$$\sum_{k=0}^{\infty} x^{-k} = \frac{1}{1 - x^{-1}}$$

Thus.

$$\begin{split} F^*(s) &= \frac{1}{2j} \left[\frac{1}{1 - e^{-T(s - j\omega)}} - \frac{1}{1 - e^{-T(s + j\omega)}} \right] = \frac{1}{2j} \left[\frac{e^{-Ts} e^{j\omega T} - e^{-Ts} e^{j\omega T}}{1 - (e^{-Ts} e^{j\omega T} - e^{-Ts} e^{j\omega T}) + e^{-2Ts}} \right] \\ &= e^{-Ts} \left[\frac{\sin(\omega T)}{1 - e^{-Ts} 2\cos(\omega T) + e^{-2Ts}} \right] = \frac{z^{-1} \sin(\omega T)}{1 - 2z^{-1} \cos(\omega T) + z^{-2}} \end{split}$$

13.2

$$F(z) = \frac{z(z+1)(z+2)}{(z-0.5)(z-0.7)(z-0.9)}$$

$$\frac{F(z)}{z} = \frac{z(z+1)(z+2)}{(z-0.5)(z-0.7)(z-0.9)}$$

$$= 46.875 \frac{z}{z-0.5} - 114.75 \frac{1}{z-0.7} + 68.875 \frac{z}{z-0.9}$$

$$F(z) = 46.875 \frac{z}{z-0.5} - 114.75 \frac{z}{z-0.7} + 68.875 \frac{z}{z-0.9},$$

$$f(kT) = 46.875(0.5)^k - 114.75(0.7)^k + 68.875(0.9)^k$$


13.3

Since
$$G(s) = (1 - e^{-Ts}) \frac{8}{s(s+4)}$$
,
 $G(z) = (1 - z^{-1})z \left\{ \frac{8}{s(s+4)} \right\} = \frac{z-1}{z} z \left\{ \frac{A}{s} + \frac{B}{s+4} \right\} = \frac{z-1}{z} z \left\{ \frac{2}{s} + \frac{2}{s+4} \right\}$.
Let $G_2(s) = \frac{2}{s} + \frac{2}{s+4}$. Therefore, $g_2(t) = 2 - 2e^{-4t}$, or $g_2(kT) = 2 - 2e^{-4kT}$.
Hence, $G_2(z) = \frac{2z}{z-1} - \frac{2z}{z-e^{-4T}} = \frac{2z(1-e^{-4T})}{(z-1)(z-e^{-4T})}$.

Therefore,
$$G(z) = \frac{z-1}{z}G_2(z) = \frac{2(1-e^{-4T})}{(z-e^{-4T})}$$
.
For $T = \frac{1}{4}s$, $G(z) = \frac{1.264}{z-0.3679}$.

13.4

Add phantom samplers to the input, feedback after H(s), and to the output. Push $G_1(s)G_2(s)$, along with its input sampler, to the right past the pickoff point and obtain the block diagram shown below.



Hence,
$$T(z) = \frac{G_1 G_2(z)}{1 + H G_1 G_2(z)}$$
.

13.5

Let
$$G(s) = \frac{20}{s+5}$$
. Let $G_2(s) = \frac{G(s)}{s} = \frac{20}{s(s+5)} = \frac{4}{s} - \frac{4}{s+5}$. Taking the inverse

Laplace transform and letting t = kT, $g_2(kT) = 4 - 4e^{-5kT}$. Taking the z-transform

yields
$$G_2(z) = \frac{4z}{z-1} - \frac{4z}{z-e^{-5T}} = \frac{4z(1-e^{-5T})}{(z-1)(z-e^{-5T})}$$
.

Now,
$$G(z) = \frac{z-1}{z} - G_2(z) = \frac{4(1-e^{-5T})}{(z-e^{-5T})}$$
.

Finally,
$$T(z) = \frac{G(z)}{1 + G(z)} = \frac{4(1 - e^{-5T})}{z - 5e^{-5T} + 4}$$
.

The pole of the closed-loop system is at $5e^{-5T} - 4$. Substituting values of T, we find that the pole is greater than 1 if T > 0.1022 s. Hence, the system is stable for 0 < T < 0.1022 s.

13.6

Substituting $z = \frac{s+1}{s-1}$ into $D(z) = z^3 - z^2 - 0.5z + 0.3$, we obtain $D(s) = s^3 - 8s^2 - 27s - 6$. The Routh table for this polynomial is shown below.

s^3	1	-27
s^2	-8	-6
s^1	-27.75	0
s^0	-6	0

Since there is one sign change, we conclude that the system has one pole outside the unit circle and two poles inside the unit circle. The table did not produce a row of zeros and thus, there are no $j\omega$ poles. The system is unstable because of the pole outside the unit circle.

13.7

Defining G(s) as $G_1(s)$ in cascade with a zero-order-hold,

$$G(s) = 20(1 - e^{-Ts}) \left[\frac{(s+3)}{s(s+4)(s+5)} \right] = 20(1 - e^{-Ts}) \left[\frac{3/20}{s} + \frac{1/4}{(s+4)} - \frac{2/5}{(s+5)} \right].$$


Taking the z-transform yields

$$G(z) = 20 \left(1 - z^{-1}\right) \left[\frac{(3/20)z}{z-1} + \frac{(1/4)z}{z - e^{-4T}} - \frac{(2/5)z}{z - e^{-5T}} \right] = 3 + \frac{5(z-1)}{z - e^{-4T}} - \frac{8(z-1)}{z - e^{-5T}}.$$

Hence for T=0.1 second, $K_p=\lim_{z\to 1}G(z)=3$, and $K_{\rm v}=\frac{1}{T}\lim_{z\to 1}(z-1)G(z)=0$, and $K_{\rm a}=\frac{1}{T^2}\lim_{z\to 1}(z-1)^2G(z)=0$. Checking for stability, we find that the system is stable for T=0.1 second, since $T(z)=\frac{G(z)}{1+G(z)}=\frac{1.5z-1.109}{z^2+0.222z-0.703}$ has poles inside the unit circle at -0.957 and +0.735. Again, checking for stability, we find that the system is unstable for T=0.5 second, since $T(z)=\frac{G(z)}{1+G(z)}=\frac{3.02z-0.6383}{z^2+2.802z-0.6272}$ has poles inside and outside the unit circle at +0.208 and -3.01, respectively.

13.8

Draw the root locus superimposed over the $\zeta = 0.5$ curve shown below. Searching along a 54.3° line, which intersects the root locus and the $\zeta = 0.5$ curve, we find the point $0.587/54.3^{\circ} = (0.348 + j 0.468)$ and K = 0.31.




13.9

Let

$$G_e(s) = G(s)G_c(s) = \frac{100K}{s(s+36)(s+100)} \frac{2.38(s+25.3)}{(s+60.2)} = \frac{342720(s+25.3)}{s(s+36)(s+100)(s+60.2)}.$$

The following shows the frequency response of $G_e(j\omega)$.



We find that the zero dB frequency, ω_{Φ_M} , for $G_e(j\omega)$ is 39 rad/s. Using Astrom's guideline the value of T should be in the range, $0.15/\omega_{\Phi_M}=0.0038$ second to $0.5/\omega_{\Phi_M}=0.0128$ second. Let us use T=0.001 second. Now find the Tustin transformation for the compensator. Substituting $s=\frac{2(z-1)}{T(z-1)}$ into $G_c(s)=\frac{2.38(s+25.3)}{(s+60.2)}$ with T=0.001 second yields

$$G_c(z) = 2.34 \frac{(z - 0.975)}{(z - 0.9416)}.$$

13.10

 $G_c(z) = \frac{X(z)}{E(z)} = \frac{1899z^2 - 3761z + 1861}{z^2 - 1.908z + 0.9075}.$ Cross-multiply and obtain $(z^2 - 1.908z + 0.9075X(z)) = (1899z^2 - 3761z + 1861)E(z)$. Solve for the highest power of z operating on the output, X(z), and obtain $z^2X(z) = (1899z^2 - 3761z + 1861)E(z) - (-1.908z + 0.9075)X(z)$. Solving for X(z) on the left-hand side yields

 $X(z) = (1899 - 3761z^{-1} + 1861z^{-2}) \ E(z) - (-1.908z^{-1} + 0.9075z^{-2})X(z)$. Finally, we implement this last equation with the following flow chart:

