

ZFOD-Zubair Field Op.Div.

WORK ORDER EXECUTION REPORT

Work Order 220001771128 Scheduling Start Date 12.07.2026 - Scheduling Finish Date 12.07.2026, WO Print Date 07.07.2026				
First Scheduled Dates		Original Planned Start Date 12.07.2026 - Original Planned Finish Date 12.07.2026		
Work Description		RELAYS FOR CUBICLE FOR GENERATOR PROTECT		
Superior Order				
Sup. Order Description				
Functional Location		Z019-4701-11CHA10 CUBICLE FOR GENERATOR PROTECTION		
Equipment				
Equipment Manufacturer				
Model Number				
Serial Number				
Work Permit				
WO Type	Work Type	Activity Type	Status	WBS Element
PM02	PM	RO Routine	APPR	6EIQ02036MA0005

Object List				
Equipment	Equipment Description	Equipment Tag	Functional Location	Functional Location Description
			Z019-4701-11CHA10-F311	GENERATOR PROTECTION RELAY
			Z019-4701-11CHA10-F312	GSU TRANSFORMER PROTECTION RELAY
			Z019-4701-11CHA10-F314	EXCITATION TRANSFORMER PROTECTION RELAY
			Z019-4701-11CHA10-F316	SST TRANSFORMER PROTECTION RELAY
			Z019-4701-11CHA10-F321	GENERATOR PROTECTION RELAY
			Z019-4701-11CHA10-F322	GSU TRANSFORMER PROTECTION RELAY
			Z019-4701-11CHA10-F324	EXCITATION TRANSFORMER PROTECTION RELAY
			Z019-4701-11CHA10-F326	SST TRANSFORMER PROTECTION RELAY
			Z019-4701-11CHA10-A47	GENERATOR PROTECTION RELAY (20HZ GENERAT



ZFOD-Zubair Field Op.Div.

WORK ORDER EXECUTION REPORT

Work Order 220001771128 Scheduling Start Date 12.07.2026 - Scheduling Finish Date 12.07.2026, WO Print Date 07.07.2026	
First Scheduled Dates	Original Planned Start Date 12.07.2026 - Original Planned Finish Date 12.07.2026
Work Description	RELAYS FOR CUBICLE FOR GENERATOR PROTECT
Superior Order	
Sup. Order Description	
Functional Location	Z2019-4701-11CHA10 CUBICLE FOR GENERATOR PROTECTION
Equipment	
Equipment Manufacturer	
Model Number	
Serial Number	
Work Permit	

Object List				
Equipment	Equipment Description	Equipment Tag	Functional Location	Functional Location Description
			Z2019-4701-11CHA10-A46	GENERATOR PROTECTION RELAY (FILTER 20HZ)
			Z2019-4701-11CHA10-K311	TRIP HV CB LOCKOUT RELAY
			Z2019-4701-11CHA10-K312	TRIP GCB LOCKOUT RELAY
			Z2019-4701-11CHA10-K313	TRIP EXCITATION CB LOCKOUT RELAY
			Z2019-4701-11CHA10-K314	TRIP GT PLST LOCKOUT RELAY

Main Discipline	ELE	Electrical
PM Plan	2881	
PM Plan Description	RELAYS FOR CUBICLE FOR GENERATOR PROTECT	
Planner Group	PIS	PPG/HVPT Inspectio
Main Work Center	19ELEC	
Failure Mode		
Failure Cause		
Failure Consequence		
D. Time Hours	0,00	



ZFOD-Zubair Field Op.Div.

WORK ORDER EXECUTION REPORT

Work Order 220001771128 Scheduling Start Date 12.07.2026 - Scheduling Finish Date 12.07.2026, WO Print Date 07.07.2026

First Scheduled Dates Original Planned Start Date 12.07.2026 - Original Planned Finish Date 12.07.2026

Work Description	RELAYS FOR CUBICLE FOR GENERATOR PROTECT		
Superior Order			
Sup. Order Description			
Functional Location	Z019-4701-11CHA10	CUBICLE FOR GENERATOR PROTECTION	
Equipment			
Equipment Manufacturer			
Model Number			
Serial Number			
Work Permit			

Action Taken

Manhours Required:			
W. Centers	W.C. Description	Num	Hrs
Tool Required:			
Code	Description	Q.ty	Hrs

Operation List:					
Op.	Sub. Op.	Work Center	Description	Persons	Actual Man Hours
0010		19ELEC	ELECTRICAL PROTECTION MAINTENANCE_1M	2	
ELECTRICAL PROTECTION MAINTENANCE_1M 10,,INFORM THE CONTROL ROOM OF BEGINNING OF THE WORKS AND OPEN THE WORK PERMIT 20,,CHECK ITEM SUBJECTS TO MAINTENANCE FOR HSE CONDITIONS 40,,VISUAL CHECK THE PROTECTION RELAY INDICATION LED 30,,VISUAL CHECK THE PANEL COMPONENT 40,,CARRY OUT VISUAL INSPECTION OF THE EQUIPMENT. MAKE SURE ARE NOT ANY DAMAGES, CHECK COMPONENTS AND CABLES FOR SIGNS OF DAMAGE OR OVERHEATING 50,,VISUAL INSPECTION THAT ALL CONNECTIONS ARE NOT DAMAGED 60,,CHECK FOR ANY UNUSUAL SOUNDS AND ODORS BECAUSE THESE SIGNS MIGHT BE THE FIRST INDICATION OF A POTENTIAL MALFUNCTION 70,,INFORM CONTROL ROOM OF ENDING OF THE WORKS 80,,PREPARE FINAL CHECK REPORT 90,,CLOSE AND CHECK IF THE WORK PERMIT HAS BEEN CORRECTLY SIGNED					



ZFOD-Zubair Field Op.Div.

WORK ORDER EXECUTION REPORT

Work Order 220001771128 Scheduling Start Date 12.07.2026 - Scheduling Finish Date 12.07.2026, WO Print Date 07.07.2026

First Scheduled Dates Original Planned Start Date 12.07.2026 - Original Planned Finish Date 12.07.2026

Work Description	RELAYS FOR CUBICLE FOR GENERATOR PROTECT	
Superior Order		
Sup. Order Description		
Functional Location	Z019-4701-11CHA10	CUBICLE FOR GENERATOR PROTECTION
Equipment		
Equipment Manufacturer		
Model Number		
Serial Number		
Work Permit		

Signatures

Work Done

Remarks

	Name	Date
WO Waiting for Scheduling	Ebied Abouelmagd Hamed	07.07.2026
WO Waiting for material by		
WO Waiting for Plant		
WO Waiting for approval	Ebied Abouelmagd Hamed	07.07.2026
WO Approved by	Ebied Abouelmagd Hamed	07.07.2026
WO Approved by		



ZFOD-Zubair Field Op.Div.

WORK ORDER EXECUTION REPORT

Work Order 220001771129 Scheduling Start Date 12.07.2026 - Scheduling Finish Date 12.07.2026, WO Print Date 07.07.2026				
First Scheduled Dates		Original Planned Start Date 12.07.2026 - Original Planned Finish Date 12.07.2026		
Work Description		RELAYS FOR CUBICLE FOR GENERATOR PROTECT		
Superior Order				
Sup. Order Description				
Functional Location		Z019-4702-12CHA10		

Object List				
Equipment	Equipment Description	Equipment Tag	Functional Location	Functional Location Description
			Z019-4702-12CHA10-F311	GENERATOR PROTECTION RELAY
			Z019-4702-12CHA10-F312	GSU TRANSFORMER PROTECTION RELAY
			Z019-4702-12CHA10-F314	EXCITATION TRANSFORMER PROTECTION RELAY
			Z019-4702-12CHA10-F316	SST TRANSFORMER PROTECTION RELAY
			Z019-4702-12CHA10-F321	GENERATOR PROTECTION RELAY
			Z019-4702-12CHA10-F322	GSU TRANSFORMER PROTECTION RELAY
			Z019-4702-12CHA10-F324	EXCITATION TRANSFORMER PROTECTION RELAY
			Z019-4702-12CHA10-F326	SST TRANSFORMER PROTECTION RELAY
			Z019-4702-12CHA10-A47	GENERATOR PROTECTION RELAY (20HZ GENERAT



ZFOD-Zubair Field Op.Div.

WORK ORDER EXECUTION REPORT

Work Order 220001771129 Scheduling Start Date 12.07.2026 - Scheduling Finish Date 12.07.2026, WO Print Date 07.07.2026

First Scheduled Dates Original Planned Start Date 12.07.2026 - Original Planned Finish Date 12.07.2026

Work Description	RELAYS FOR CUBICLE FOR GENERATOR PROTECT		
Superior Order			
Sup. Order Description			
Functional Location	Z019-4702-12CHA10	CUBICLE FOR GENERATOR PROTECTION	
Equipment			
Equipment Manufacturer			
Model Number			
Serial Number			
Work Permit			

Object List				
Equipment	Equipment Description	Equipment Tag	Functional Location	Functional Location Description
			Z2019-4702-12CHA10-A46	GENERATOR PROTECTION RELAY (FILTER 20HZ)
			Z2019-4702-12CHA10-K311	TRIP HV CB LOCKOUT RELAY
			Z2019-4702-12CHA10-K312	TRIP GCB LOCKOUT RELAY
			Z2019-4702-12CHA10-K313	TRIP EXCITATION CB LOCKOUT RELAY
			Z2019-4702-12CHA10-K314	TRIP GT PLST LOCKOUT RELAY

Main Discipline	ELE	Electrical
PM Plan	2904	
PM Plan Description	RELAYS FOR CUBICLE FOR GENERATOR PROTECT	
Planner Group	PIS	PPG/HVPT Inspectio
Main Work Center	19ELEC	
Failure Mode		
Failure Cause		
Failure Consequence		
D. Time Hours	0,00	



ZFOD-Zubair Field Op.Div.

WORK ORDER EXECUTION REPORT

Work Order 220001771129 Scheduling Start Date 12.07.2026 - Scheduling Finish Date 12.07.2026, WO Print Date 07.07.2026


First Scheduled Dates Original Planned Start Date 12.07.2026 - Original Planned Finish Date 12.07.2026

Work Description	RELAYS FOR CUBICLE FOR GENERATOR PROTECT		
Superior Order			
Sup. Order Description			
Functional Location	Z019-4702-12CHA10	CUBICLE FOR GENERATOR PROTECTION	
Equipment			
Equipment Manufacturer			
Model Number			
Serial Number			
Work Permit			

Action Taken	
---------------------	--

Manhours Required:			
W. Centers	W.C. Description	Num	Hrs
Tool Required:			
Code	Description	Q.ty	Hrs

Operation List:					
Op.	Sub. Op.	Work Center	Description	Persons	Actual Man Hours
0010		19ELEC	ELECTRICAL PROTECTION MAINTENANCE_1M	2	
ELECTRICAL PROTECTION MAINTENANCE_1M 10,,INFORM THE CONTROL ROOM OF BEGINNING OF THE WORKS AND OPEN THE WORK PERMIT 20,,CHECK ITEM SUBJECTS TO MAINTENANCE FOR HSE CONDITIONS 40,,VISUAL CHECK THE PROTECTION RELAY INDICATION LED 30,,VISUAL CHECK THE PANEL COMPONENT 40,,CARRY OUT VISUAL INSPECTION OF THE EQUIPMENT. MAKE SURE ARE NOT ANY DAMAGES, CHECK COMPONENTS AND CABLES FOR SIGNS OF DAMAGE OR OVERHEATING 50,,VISUAL INSPECTION THAT ALL CONNECTIONS ARE NOT DAMAGED 60,,CHECK FOR ANY UNUSUAL SOUNDS AND ODORS BECAUSE THESE SIGNS MIGHT BE THE FIRST INDICATION OF A POTENTIAL MALFUNCTION 70,,INFORM CONTROL ROOM OF ENDING OF THE WORKS 80,,PREPARE FINAL CHECK REPORT 90,,CLOSE AND CHECK IF THE WORK PERMIT HAS BEEN CORRECTLY SIGNED					



ZFOD-Zubair Field Op.Div.

WORK ORDER EXECUTION REPORT

Work Order 220001771129 Scheduling Start Date 12.07.2026 - Scheduling Finish Date 12.07.2026, WO Print Date 07.07.2026

First Scheduled Dates Original Planned Start Date 12.07.2026 - Original Planned Finish Date 12.07.2026

Work Description	RELAYS FOR CUBICLE FOR GENERATOR PROTECT	
Superior Order		
Sup. Order Description		
Functional Location	Z019-4702-12CHA10	CUBICLE FOR GENERATOR PROTECTION
Equipment		
Equipment Manufacturer		
Model Number		
Serial Number		
Work Permit		

Signatures

Work Done

Remarks

	Name	Date
WO Waiting for Scheduling	Ebied Abouelmagd Hamed	07.07.2026
WO Waiting for material by		
WO Waiting for Plant		
WO Waiting for approval	Ebied Abouelmagd Hamed	07.07.2026
WO Approved by	Ebied Abouelmagd Hamed	07.07.2026
WO Approved by		



ZFOD-Zubair Field Op.Div.

WORK ORDER EXECUTION REPORT

Work Order 220001771130 Scheduling Start Date 12.07.2026 - Scheduling Finish Date 12.07.2026, WO Print Date 07.07.2026

First Scheduled Dates Original Planned Start Date 12.07.2026 - Original Planned Finish Date 12.07.2026

Work Description		RELAYS FOR CUBICLE FOR CONTROLLER		
Superior Order				
Sup. Order Description				
Functional Location		Z019-4702-12CUA11CUBICLE FOR CONTROLLER		
Equipment				
Equipment Manufacturer				
Model Number				
Serial Number				
Work Permit				
WO Type	Work Type	Activity Type	Status	WBS Element
PM02	PM	RO Routine	APPR	6EIQ02036MA0005

Object List				
Equipment	Equipment Description	Equipment Tag	Functional Location	Functional Location Description
			Z019-4702-12CUA11-R	GTG EXCITATION SFC CONTROLLER PANEL #
			Z019-4702-12CUA11-F155	ROTOR EARTH FAULT MONIT

Main Discipline	ELE	Electrical
PM Plan	2906	
PM Plan Description	RELAYS FOR CUBICLE FOR CONTROLLER	
Planner Group	PIS	PPG/HVPT Inspectio
Main Work Center	19ELEC	
Failure Mode		
Failure Cause		
Failure Consequence		
D. Time Hours	0,00	
Action Taken		

Manhours Required:			
W. Centers	W.C. Description	Num	Hrs



ZFOD-Zubair Field Op.Div.

WORK ORDER EXECUTION REPORT

Work Order 220001771130 Scheduling Start Date 12.07.2026 - Scheduling Finish Date 12.07.2026, WO Print Date 07.07.2026

First Scheduled Dates Original Planned Start Date 12.07.2026 - Original Planned Finish Date 12.07.2026

Work Description	RELAYS FOR CUBICLE FOR CONTROLLER		

Tool Required:			
Code	Description	Q.ty	Hrs

Operation List:					
Op.	Sub. Op.	Work Center	Description	Persons	Actual Man Hours



ZFOD-Zubair Field Op.Div.

WORK ORDER EXECUTION REPORT

Work Order 220001771130 Scheduling Start Date 12.07.2026 - Scheduling Finish Date 12.07.2026, WO Print Date 07.07.2026	
First Scheduled Dates Original Planned Start Date 12.07.2026 - Original Planned Finish Date 12.07.2026	
Work Description	RELAYS FOR CUBICLE FOR CONTROLLER
Superior Order	
Sup. Order Description	
Functional Location	Z019-4702-12CUA11 CUBICLE FOR CONTROLLER
Equipment	
Equipment Manufacturer	
Model Number	
Serial Number	
Work Permit	

0010		19ELEC	ELECTRICAL PROTECTION MAINTENANCE_1Y	2	
ELECTRICAL PROTECTION MAINTENANCE_1Y ELECTRICAL PROTECTION MAINTENANCE_1Y 10,,INFORM THE CONTROL ROOM OF BEGINNING OF THE WORKS AND OPEN THE WORK PERMIT,,,, 20,,CHECK ITEM SUBJECTS TO MAINTENANCE FOR HSE CONDITIONS,,,, 30,,CARRY OUT TOOLBOX TALK MEETING 40,,CARRY OUT AND CONFIRM ELECTRICAL ISOLATION,,,,,,,,, 50,,OPEN PTW 60,,CHECK CONDITION OF TOOLS, ACCESSORIES, AND AUXILIARY MATERIALS TO MAINTENANCE FOR HSE CONDITIONS AND PLACE THEM IN SAFE 70,,VISUAL INSPECTION AND CHECK FOR THE GENERAL STATUS OF PANELS (AUX RELAYS, MCB, TB#) 80,,EXTRACT PROTECTION RELAY DATA AND CHECK IT 90,,VERIFY LOCAL INDICATION INSTRUMENT (A AND V) 100,,CLEANING AND TIGHTENING FOR ALL PANELS COMPONENTS 110,,CHECK THE PROTECTION RELAY HMI 120,,CHECK ANY ALARM OR ABNORMAL CONDITION 130,,CHECK THE ACTIVATION OF PROTECTION FUNCTIONS 140,,TEST THE PROTECTION RELAY USING SECONDARY INJECTION TESTER, AND MAKE A TRIP TEST FOR THE CB BY THE RELAY BY CLOSING THE CB IN TEST POSITION (IF APPLICABLE) 150,,INFORM THE AREA AUTHORIZED PERSON THAT THE JOB HAS COMPLETED 160,,CLOSE AND CHECK IF THE WORK PERMIT HAS BEEN CORRECTLY SIGNED					



ZFOD-Zubair Field Op.Div.

WORK ORDER EXECUTION REPORT

Work Order 220001771130 Scheduling Start Date 12.07.2026 - Scheduling Finish Date 12.07.2026, WO Print Date 07.07.2026

First Scheduled Dates Original Planned Start Date 12.07.2026 - Original Planned Finish Date 12.07.2026

Work Description	RELAYS FOR CUBICLE FOR CONTROLLER	
Superior Order		
Sup. Order Description		
Functional Location	Z019-4702-12CUA11	CUBICLE FOR CONTROLLER
Equipment		
Equipment Manufacturer		
Model Number		
Serial Number		
Work Permit		

Signatures

Work Done

Remarks

	Name	Date
WO Waiting for Scheduling	Ebied Abouelmagd Hamed	07.07.2026
WO Waiting for material by		
WO Waiting for Plant		
WO Waiting for approval	Ebied Abouelmagd Hamed	07.07.2026
WO Approved by	Ebied Abouelmagd Hamed	07.07.2026
WO Approved by		