



ZFOD-Zubair Field Op.Div.

WORK ORDER EXECUTION REPORT

Work Order 210000346118 Scheduling Start Date 11.07.2026 - Scheduling Finish Date 18.07.2026, WO Print Date 12.07.2026

First Scheduled Dates Original Planned Start Date 11.07.2026 - Original Planned Finish Date 18.07.2026

Work Description	CARRY OUT CM TO CHECK AND FIX FLAME DETECTOR FAULT AT GAS AREA
Superior Order	
Sup. Order Description	
Functional Location	Z019-7000-90CYE07CR036 TRIPLE IR FLAME DETECTOR FG IN PP & SS
Equipment	
Equipment Manufacturer	
Model Number	
Serial Number	
Work Permit	

Operation List:					
Op.	Sub. Op.	Work Center	Description	Persons	Actual Man Hours
0010		19FAG	FLAME DETECTOR FAULT AT GAS AREA	0	



ZFOD-Zubair Field Op.Div.

WORK ORDER EXECUTION REPORT

Work Order 210000346118 Scheduling Start Date 11.07.2026 - Scheduling Finish Date 18.07.2026, WO Print Date 12.07.2026

First Scheduled Dates Original Planned Start Date 11.07.2026 - Original Planned Finish Date 18.07.2026

Work Description	CARRY OUT CM TO CHECK AND FIX FLAME DETECTOR FAULT AT GAS AREA	
Superior Order		
Sup. Order Description		
Functional Location	Z019-7000-90CYE07CR036	TRIPLE IR FLAME DETECTOR FG IN PP & SS
Equipment		
Equipment Manufacturer		
Model Number		
Serial Number		
Work Permit		

Signatures

Work Done

Remarks

	Name	Date
WO Waiting for Scheduling		12.07.2026
WO Waiting for material by		
WO Waiting for Plant		
WO Waiting for approval	AMMAR SAEED HAIDER	12.07.2026
WO Approved by	AMMAR SAEED HAIDER	12.07.2026
WO Approved by		