


## LAD 101 - SEER\_1 - SEER\_1 --- Total Rungs in File = 16



## LAD 101 - SEER\_1 - SEER\_1 --- Total Rungs in File = 16



LAD 101 - SEER\_1 - SEER\_1 --- Total Rungs in File = 16



LAD 101 - SEER\_1 - SEER\_1 --- Total Rungs in File = 16

```
CORRECTIVE ACTION REGISTER
         - WHEN MACHINE IS RUNNING WITHOUT FAULTS (STATE = 4)
        ---- (FORCE) SET CORRECTIVEACTION = 0
---- (FORCE) SET ALARM = 0
        -- REQUIRED
        ---- 0 = NONE ENTERED
---- 2 = SCHEDULED DOWN OR CLEANING
         --- 3 = OPERATOR ON LUNCH OR BREAK
         ---- 1 DOES NOT EXIST - DEPRECATED AFTER INITIAL DEPLOYMENT
         ---- 2 AND 3 ARE SET BY SEER, NOT BY THE LOCAL CONTROLLER
            SEER IO 0
                                                                                                                                                              SEER IO 0
                                                                                                                                                              -- DISCRETE COMM
            -- DISCRETE COMM
            -- MACHINE STATE
                                                                                                                                                              -- CORRECTIVE ACTION
                   -EQU
                                                                                                                                                                    -MOV
0011
               Equal
                                                                                                                                                                 Move
                Source A
                            N100:4
                                                                                                                                                                                  0<
                                0<
                                                                                                                                                                             N100:5
0<
               Source B
                                 4
4<
                                                                                                                                                              SEER IO 0
                                                                                                                                                              -- DISCRETE COMM
                                                                                                                                                              -- ALARM STATE
                                                                                                                                                                    -MOV
                                                                                                                                                                 Move
                                                                                                                                                                                  0<
                                                                                                                                                                             N100:2
                                                                                                                                                                                  0<
        ACTIVE JOB HOLDING REGISTERS
         -- REQUIRED
         ---- OPERATOR ID (FLOAT OR BIGINT)
        -- -- JOB NUMBER (FLOAT OR BIGINT)
-- -- SCHEDULE NUMBER (FLOAT OR BIGINT)
         ---- DO -NOT- EXECUTE LOGIC UPON THESE REGISTERS, THEY EXIST
           PURELY FOR USE BY SEER, WHICH WILL WRITE AND READ BACK
           DATA AS NEEDED.
- THE 'ALWAYS FALSE' BIT IN FRONT OF THIS RUNG RENDERS
            THIS LADDER AS NOTHING MORE THAN A PLACEHOLDER FOR
           YOUR REFERENCE.
            SEER IO 0
            -- DISCRETE COMM
            -- ALWAYS FALSE
INSTRUCTION
(ALWAYS = 0)
N100:0
                                                                                                                                                             SEER IO 1
-- ANALOG COMM
                                                                                                                                                              -- JOB NUMBER
                                                                                                                                                                     -ADD
0012
                                                                                                                                                                 Add
                    10
                                                                                                                                                                             F101:2
                                                                                                                                                                 Source A
                                                                                                                                                                                 0.0<
                                                                                                                                                                 Source B
                                                                                                                                                                                 0.0
                                                                                                                                                                                 0.0<
                                                                                                                                                                             F101:2
                                                                                                                                                                 Dest
                                                                                                                                                                                 0.0<
                                                                                                                                                             SEER IO 1
                                                                                                                                                             -- ANALOG COMM
                                                                                                                                                              -- SCHEDULE NUMBER
                                                                                                                                                                     -ADD
                                                                                                                                                                 Add
                                                                                                                                                                             F101:3
                                                                                                                                                                 Source A
                                                                                                                                                                 Source B
                                                                                                                                                                                 0.0
                                                                                                                                                                                 0.0<
                                                                                                                                                                 Dest
                                                                                                                                                                             F101:3
                                                                                                                                                                                 0.0<
                                                                                                                                                             SEER IO 1
-- ANALOG COMM
                                                                                                                                                              -- OPERATOR ID
                                                                                                                                                                     -ADD
                                                                                                                                                                 Add
                                                                                                                                                                             F101:4
                                                                                                                                                                 Source A
                                                                                                                                                                                 0.0<
                                                                                                                                                                 Source B
                                                                                                                                                                                 0.0
                                                                                                                                                                                 0.0<
                                                                                                                                                                 Dest
                                                                                                                                                                             F101:4
                                                                                                                                                                                 0.0<
```

LAD 101 - SEER\_1 --- Total Rungs in File = 16

