Motor Driver Board_Pitch Or Roll

- 01_INDEX
- 02_Block Diagram
- 03_Power
- 04_STM32
- 05_MOS Driver
- 06_3H-Bridges MOS+Shunt Resistor
- 07_Phase Current and Voltage Sensor
- 08_MA700

Change List

01_Vesion 1.0 Created at 2017/4/4

XD.N09001AA

02_Vesion 1.1 Created at 2017/5/5

XD.N09001BA

- 01_Fixed phase current amplifying circuit bias bug
- 02_Delete reset button
- 03_Re-layout MA700

for correct magnetic field direction measurement

04_Add Test Point for externally mount MA700









