PHARMACOVIGILANCE DEVIATION REPORT

Deviation ID: PV-2026-0447
Product: Amlodipine Besylate Tablets, 10mg
Batch Number: AB-2026-1183
Site: Manufacturing Facility 3, Pune

Description of Deviation:
During in-process quality control, tablet hardness readings for 3 of 20 sampled units fell below the validated specification of 8-12 kp, with readings of 6.2, 6.8, and 7.1 kp respectively.

Root Cause Investigation:
Compression force on the tablet press (Station 4) was found to have drifted below the validated setpoint due to a worn punch tip. Preventive maintenance records indicate the punch set was 340 operating hours past its scheduled inspection interval.

Impact Assessment:
Batch AB-2026-1183 (net yield: 480,000 tablets) placed on quality hold pending full characterization. Dissolution testing scheduled per SOP-QC-114.

CAPA Actions:
1. Replace punch tip set on Station 4 (Completed)
2. Revise PM schedule to 250-hour inspection interval (In Progress)
3. Retrospective review of prior 6 months of Station 4 batches (Planned)

Regulatory Classification: Major Deviation, per ICH Q7 Section 14