pcb-s4 removed-verified screw valid-sd(star-sd) pcb-s2 removed-verified screw valid-sd(flat-sd) pcb-s1 removed-verified screw valid-sd(flat-sd) pcb-s3 removed-verified screw valid-sd(flat-sd) motor-axis component chip chip-a0 at-side(bottom) has-affordance *has-confidence(medium)* clear pliers-point removable-component pcb-a2 *has-confidence(medium)* pcb-s0 lever-point removed-verified has-affordance screw *valid-sd(flat-sd)* pcb-a0 *has-confidence(low)* lever-point has-affordance pcb pcb-a3 has-affordance clear *has-confidence(high)* removable-component lever-point has-affordance removed-verified has-affordance pcb-a1 *has-confidence(medium)* lever-point pcb-a4 *has-confidence(high)* pliers-point