













	2	3 4	5	6
H				
		A power step up circuit can be assembled here.		
		can be assembled here.		
R				
	<u> </u>			
Н				
		Sheet /Sning	dle PSU/	
		Sheet: /Spino File: spindleF	PSILsch	
		The Spinder	and FluidNC CNC Cantague	
		Title: Trin	amic FluidNC CNC Controller	
		Size: A4	Date: 2022-01-27 eeschema 5.1.12-84ad8e8a8692ubuntu21.04.1	Rev: 1.0.0
		KiCad F D A	eeschema 5.1.12-84ad8e8a8692uhuntu21.04.1	ld: 8/17
	3	3 4	5	10. 0/ 1/
1 1				

















