


#### Frequency.of.O&M - attrapp.score 1




#### Temperature.range - attrapp.score 1




Slope - attrapp.score 1




#### Soil.type/hydraulic.conductivity - attrapp.score (




Groundwater.depth - attrapp.score 1




Excavation - attrapp.score 1



# onstruction.skills - attrapp.score 0.91723381970




## Design.skills - attrapp.score 1




#### leach.field, Katarniya - techapp.score 0.950904602031079


### O&M.skills - attrapp.score 1




#### Management - attrapp.score 0.943




Pipe.supply - attrapp.score 1




### Concrete.supply - attrapp.score 1



Spare.parts.supply - attrapp.score 0.9685



Surface.area.offsite - attrapp.score 1



## population.change.rate - attrapp.score 1

