


#### Frequency.of.O&M - attrapp.score 1


#### emperature.range – attrapp.score 0.79318193011






### /ehicular.access - attrapp.score 0.94239615159Soil.type/hydraulic.conductivity - attrapp.score (







#### roundwater.depth - attrapp.score 0.97449979696




## Excavation – attrapp.score 1



#### Population.density - attrapp.score 1




# Construction.skills - attrapp.score 1




### double.pit, Katarniya - techapp.score 0.970460699222404


### Design.skills - attrapp.score 1




### O&M.skills - attrapp.score 1



#### Management – attrapp.score 0.9535



## Spare.parts.supply - attrapp.score 1



### Surface.area.onsite - attrapp.score 1

