

Temperature and Humidity Sensor SHTC3 Breakout

The SHTC3 breakout board precisely measures temperature and humidity, featuring easy I2C connectivity and low power consumption.

Key specifications

IC	SHTC3
Measurement Types	Temperature, Humidity
Measurement Range	Temperature -40°C to 125°C; Humidity 0 to 100 %RH
Measurement Accuracy	Temperature $\pm 0.2^{\circ}\text{C}$; Humidity $\pm 2\%$ RH
Interface	I2C
Supply voltage	3.3–5 V

Getting started

Connect it to your board with the qwiic connector or the breadboard-compatible header pins, then read data over I2C.