

GARAGE REPAIR ESTIMATE

Bavarian Auto Works - Authorised BMW Service Centre

No. 23, Industrial Estate, Guindy, Chennai - 600032 | Ph: 044-2250 1800
GSTIN: 33AABCB1234F1Z5 | Workshop Reg: TN/MV/WS/2019/4521

Estimate No: EST-2025-08-3847 Date: 16-Aug-2025
Customer: Rajesh Kumar S. Phone: +91 98412 67530
Vehicle: BMW X5 xDrive30d (2022) Reg: TN 09 CK 4521
Insurance Policy: POL-AUTO-001 Insurer: SecureLife Insurance
Odometer: 34,521 km Provider ID: PROV-002
FIR Reference: Manapakkam PS FIR #1247/2025

DETAILED REPAIR ESTIMATE

#	Description	Part No.	Qty	Parts (Rs.)	Labour (Rs.)	Total (Rs.)
1	Rear Bumper Cover - Replace	51127 389 979	1	42,500	6,500	49,000
2	Rear Bumper Absorber - Replace	51127 354 866	1	12,800	2,500	15,300
3	Tail Lamp Assy (L) - Replace	63217 422 697	1	28,500	3,000	31,500
4	Rear Quarter Panel - Repair & Paint	---	1	8,500	18,000	26,500
5	Boot Lid - Dent Repair & Polish	---	1	2,000	5,500	7,500
6	Bumper Parking Sensors - Recalibrate	66209 261 584	4	4,200	3,500	7,700
7	Paint Material & Supplies	---	1	12,500	0	12,500
8	Body Alignment & QC Check	---	1	0	8,000	8,000

Sub-Total: 1,58,000
GST @ 18%: 28,440
GRAND TOTAL: 1,86,440

Estimated Repair Duration: 7-8 working days
Warranty: 12 months on parts, 6 months on paint/body work

Notes:
- All OEM genuine BMW parts will be used.
- Additional damage, if discovered during disassembly, will be communicated.
- Vehicle must remain at workshop during repair period.

Prepared By: Arun V., Service Advisor (Ext: 204)
Approved By: Mohamed Rafi, Workshop Manager

Customer Signature: _____
Date: 16-Aug-2025