

Milestone/Gateway: Program Start Organisation: 93000 Report Week: (2016-05-31 1 242402 VEHICLE HARDWARE Report Author: Patrik Lundgren

Milestone/Gateway purpose

The purpose at <PS> is to start the program and set prerequisites, mission, targets and program finance and to get program funding approval up to <PC> (Program Confirmation).

Decisions to be taken

Decide program mission, targets and finance.

Start of program including program funding up to <PC>.

Decide if a separate LLF-decision is necessary prior to the <PC>-timing.

Decide program prerequisites including but not limited to:

- Decide Vehicle program plan (VPP).
- Confirm Single Model Selection (SMS).
- Confirm sourcing plan.
- Decide Quality target.
- Confirm Selection of technical systems:
 - Function Decision Alternative (FDA).
 - Preliminary selection of dimensional and systems (PS-systems) according to sign off plan.

Program Content

- DECOUPLE
 - 12V Enhanced Regean
 - · Body
 - Interior
 - Func Black Trim
 - 48V E-KERS
 - Body
 - Interior
 - Func Black Trim

Milestone Summar 242402 VEHICLE HARDWARE

Issue date: 1/10/19 11:42AM, Security Class: Pr

Page 1 of 5



Milestone/Gateway: Program Start 242402 VEHICLE HARDWARE

Organisation: 93000

Report Week: 1(2016-05-31 13: Report Author: Patrik Lundgre

· VEA GEN3

Exterior

· Body

· Func Black Trim

· ADAS

Interior

Exterior

· iCUP

- Face Lift

· XC90

- PM2.5

- V-PHEV

- Legal

Top Tether

- CO2

R1234YF Refrigirant US

- Labels

Issue date: 1/10/19 11:42AM, Security Class: Pr

Page 2 of 5



Milestone/Gateway: Program Start Organisation: 93000 Report Week: 1 (2016-05-31 13:4

242402 VEHICLE HARDWARE Report Author: Patrik Lundgre

Information on made agreements

- DECOUPLE
 - 12/48V & VEA GEN3
 - Not use Std battery sudy (100mm)
 - Cable routing behind load floor supprt
 - · ADAS
 - Both XC90 & S/V90
 - No changes on S/V90 soft nose & spoiler. Only lower mesh
- Face Lift
 - Only for XC90
- PM2.5
 - Only Chines market
 - Missing in-port in CCM
- V-PHEV
 - Develop so called "Flat rear floor"
- Legal
 - Top teather
 - Follow V43X concept.
 - Request from PSVL of C/O plastic covers
 - Requst from Design: Study how can the cover be smaller
- CO2
- Labels

Issue date: 1/10/19 11:42AM, Security Class: Pr

Page 3 of 5



Milestone/Gateway: Program Start Organisation: 93000 Report Week: 1(2016-05-31 13:4

242402 VEHICLE HARDWARE Report Author: Patrik Lundgre

Key open issues

VCU1 psoition

VCU1 (KERS, PHEV & BEV). differant alternatives for position. Modify B&T parts? YELLOW

12/48V Power Supply

Cable routing 48V wheel house routing not decided. for now YELLOW

VEA GEN3

VEA GEN3 might drive non integrated end pipes. YELLOW

ADAS

- Driver Monitoring Camera position in IP speaker mesh not fully devloped & approved.YELLOW
- ADAS intro V54X 519A. Unclear if main track is radar behind emblem or lwr mesh YELLOW

iCUP

iCUP drives a 4" DIM à V526 IP without FWC. Proposal to keep plastc collise w/o LED. YELLOW

V-PHEV

- · Package V-PHEV ongoing Work ongoing. Package meeting started YELLOW
- GPF package discusion initiated. YELLOW

Advanced Air Ceaner Sensor

- PM2.5 in-port in CCM is missing EE&C attention. YELLEW
- PM2.5 sensor position glove box consealing. Not loged decision. YELLOW

Face Lift

Chrome list length Too long. Should be divided. Design to come back YELLOW

Investiagtion

- · USB-C front tunnel ongoing but USB-C in 2nd row is unclear position.
- Larger tank V-PHEV: B&T Consiquenses not clarified

EXTRA

- V431 R-Design moved to 519A or not
- V431 8 exterior colors moved to 519A?
- New upholstery concept for R-design incl. a light version. Unclear

Milestone Summar 242402 VEHICLE HARDWARE

Issue date: 1/10/19 11:42AM, Security Class: Pr

Page 4 of 5



Milestone/Gateway: Program Start Organisation: 93000 Report Week: 1(2016-05-31 13:

242402 VEHICLE HARDWARE Report Author: Patrik Lundgre

Recommendations and wanted decisions

B&T UTM Recomendation: Gate open to <PC>

Milestone Summar 242402 VEHICLE HARDWARE

Issue date: 1/10/19 11:42AM, Security Class: Pr

Page 5 of 5